CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSITE20201955Address:1401 NW VIEW HIGH DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Storm - Outlet Structure		John Jackson	Partial	Wednesday, February 03, 2021	
Informational:					
1 Miso	c	Line 700 1/14/21 Thursday 705 10'x5' Junction Box . C	g Crew) installed approxima y. Today approximately 135' Contractor is continuing to in nstalled approximately 40' days work.	' of 60" RCP and structure nstall 60" RCP after 705	
Informational:					
2 Miso	c	•	; on storm Lines 700 & 2200. Overview of the days activ		
Informational:					
3 Miso	с	pipe on Line 700. Collars v	g Crew) projection are to fin were poured for 706 and inv M to pour invert for 706 and be installed today.	vert for 705 concrete	
		force to stop because of p	en Crew) installed approxir problems with structure 220 rate Inlet 1402 and installed	03. Contractor moved to	

		approximately 80' of 30" HDPE pipe. Collars were poured at 2202 Grate Inlet.
Informatio	onal:	
4	Misc	1/21/21 Thursday Contractor Clarkson worked on Lines 700, 1300 & 1400. Collars and inverts were completed on on storm Line 700. Lines 1300 approximately 132' of 24" HDPE was installed up to proposed structure 1301. Collars & inverts were poured at the storm connection of 1300 to & Structure 704 as-per project plans. Collars and invert poured on Structure 1401. On 701 & 702 invert were poured also Collar was poured on 707.
Informatio	onal:	
5	Misc	2/2/21 Tuesday Contractor Clarkson worked on Lines 705 to 901 HDPE storm pipe, & 1900 to 1901 as-per project plans 42" HDPE storm pipe.
Informatio	onal:	
6	Misc	2/3/21 Wednesday Contractor (Clarkson) poured invert & collars 901, collar 1403, and toe walls 1900 & 2200. The contractor installed structure 2203.

Comments: