| Inspection Summary | | | |
|--|---|---|---|
| Permit #: PRSUBD20211138, Development - Subdivision HIGHLAND MEADOWS 5TH PLAT Address: 1201 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081 | | | |
| This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved. | | | |
| Inspection Item: Inspection: | Inspector: | Outcome: | Date: |
| manhole 5-A1, a 138. RP 7-13-21 Informational 2 Patrick's crew so RP 7-14-21 Informational 3 Patrick's crew so RP 7-14-21 Informational 4 Patrick's crew so Informational 5 Patrick's crew so sanitary pipe fo Informational 6 MH C-1 has been the service lines | om Redford Construction on along with 220 feet of sanit | ary pipe and service lateral. They also laid over 200 for they also laid over 200 for aid 250 feet of sanitary pipes and 137. They also working towards C-2 the | eet of sanitary pipe. Teet of sanitary pipe. |
| Comments: | | | |