## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20191614 Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Rated Assembly Inspection		Robb Popp	Partial	Friday, August 13, 2021	
Informational:					
1	THIRD FLOOR	-AREAS APPROVED-			
		BUILDING C			
		COMPLETE			
		BUILDING B			
		COMPLETE			
		BUILDING A			
		COMPLETE			
Informational:					
2	SECOND FLOOR	-AREAS APPROVED-			
		BUILDING C:			
		COMPLETE			
		BUILDING B:			
		COMPLETE			
		BUILDING A:			
		COMPLETE EXCEPT AT ROO	OM 2045		
Informational:					

3	FIRST FLOOR	-AREAS APPROVED-		
		***BUILDING C***		
		COMPLETE		
		***BUILDING B***		
		COMPLETE		
		***BUILDING A***		
		CORRIDOR WALLS AND CELINGS OK FOR SOFFITS TO SHAFT WALL PRE ROCK BEHIND SHOWERS ROOMS:		
		-1016		
		RC AT LOBBY 1032		
		RC AT CEILINGS IN ROOMS1032-1035,1037,10391055,1056,1061,1062,1016,1018,1046,1047,1049,10		
		50,1052		
		OK TO INSTALL RC FOR SOFFITS IN CORRIDOR THROUGHOUT -SCREW PATTERN STAIRWELLS S1,2,3		
		-RATED LAYER AT CEILINGS: 1016,1018,1043,1044,1046,1047,1053,1053A		
		-SOFFIT AT CORRIDOR FROM BUILDING B TO ELEVATOR OK TO COVER		
		-SCREW PATTERN ROOMS: 1032,1034,1037,1039,1055,1061,1062		
		****MCAL BUILDING***		
		RM 165 NORTH WALL LAYER OVER SHAFT WALL		
		1057 WALLS FOR ELECTRICAL GEAR		
		RC OK ABOVE COOLER SCREW PATTERN AT WALLS AND CEILINGS FOR COOLER		
		RC IN CORRIDORS FIRST 16" FOR SOFFITS: CORRIDORS		
		167,176,177,177A,178A,169,172,173,39,42,31,34,48		
		PRE ROCK AT CORRIDOR SOFFITS: 176,177,177A		
		SCREW PATTERN AT CORRIDOR SOFFITS-OK FOR FRAMING: 172,173,169-		
		RC AT PRE ROCK FOR BATHROOM		
		CEILINGS:101-106,108,109-128,,130,131,133,135-137,139,140-146		
<b>6</b>		-RATED CEILING LAYER AT BATHROOMS 1046,1047		
Correctiv 4	Corrective Action Required: 4 Miscellaneous -REMOVE ROCK AT SHAFT WALLS AND 4' PIECES IN CORRODORS MCAL buldi			
4	Correction	-REMOVE ROCK AT SHAFT WALLS AND 4' PIECES IN CORRODORS MCAL bulding -SEAL ALL GAPS/PENETRATIONS IN SMOKE WALLS		

## Comments: