CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20212196

Informational:

Misc

Address: 1630 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Storm Sewer Construction Inspection		Nick Lightner	Partial	Thursday, August 19, 2021
Informati	onal:			
1	Misc	8/11/21 Wednesday		
		Contractor has installed approximately 74' of 30" HDPE CI A-1, 70' of 24 " HDPE from CI A-1 to A-2, & 73' of 24" HDPE. CI A-1, A-2, and A-3. Approximately 124' of 24" HDPE & CI B-1 was installed. Third Party Testing PSI was onsite to test street crossing and excavation in street as required.		
Informati	onal:		_	•
2	Misc	8/16/21 - Crew had to remove the 73 feet of the 24" pipe between curb inlets A-2 and A-3 due to the rain last week pushed the pipe up and out of the ground. During this process they clipped the sanitary lateral that runs to lot 382. All this was repaired and they are currently breaking rock.		
Informati	onal:	·	•	
3	Misc	out of A-3 headed up hi was 7in into the storm p	II to A-4 and the sanita pipe. Spoke to the fore	g that involve the storm line ry lateral for lot 383. The lateral man and he informed his boss at the engineering firm on this

project would be submitting over a change for this issue.

HDPE and inlet C-1 was placed.

This afternoon the crew laid out of A-3 to inlet C-1 roughly 110 feet of 18"

8/18/21 - This morning crews was digging silt out of storm boxes. Then this

afternoon storm lids was unloaded and started digging on the storm line.

Informational:

5 Misc 8/18/21 - This morning crews was digging silt out of storm boxes. Then this

afternoon storm lids was unloaded and started digging on the storm line.

Informational:

6 Misc 8/18/21 - This morning crews was digging silt out of storm boxes. Then this

afternoon storm lids was unloaded and started digging on the storm line.

Informational:

7 Misc 8/19/21 - Roughly 100ft of 15" HDPE pipe was installed between A-5 to A-6.

Concrete was on order for the boxes as well.

Comments: