

COMPLETE EXCEPT 2044

Informational:

3 FIRST FLOOR

—AREAS APPROVED—

BUILDING C

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS:1015,1017,1020-1030

STAIRWELL WALLS AND CEILING

BUILDING B

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS: 1002-1015

STAIRWELL WALLS AND CEILING

BUILDING A

CORRIDOR CEILING TO SHAFT WALL

EXTERIOR WALL 1032 OK TO INSULATE

STAIRWELL WALLS AND CEILING

ROOMS: 1016,1018,1041,1042,1043,1044,1046,1050, 1053, 1053A, 1056, 1059,

1061, 1062, 1037,1038,1049,1052,1061, 1045,1047,1048,1057,1057A,1058

ROOM 1041 OK FOR SOFFIT FRAMING

STAIRWELL WALLS AND CEILING

SOFFIT FRAMING 1049,1052, CORRIDOR1060,1036

MCAL BUILDING

--- PRE ROCK:

MECHANICAL ROOM 165 NORTH WALL

ROOM 156

Kitchen 164 OK-CEILING OK FOR ROCK NOT AT HOODS

CORRIDOR 167 TO 10' FROM SHAFT WALL

CORRIDOR 169,172,173, 34,39,42

MC EXTERIOR WALLS OK FOR FOAM

MC SHARED SPACES OK FOR RC 149-160, 162,162A, 174, 174A,175

MC UNITS 1-18, 21, 36,37

SHARED SPACES: 149,150,152,153,154,157,159,162, 174,174A, 175

AL UNITS: 102-147

Corrective Action Required:

4 Miscellaneous
Correction

2044-INCOMPLETE

2045-INCOMPLETE

024-REPAIR TRUSS

COMPLETE DRY SYSTEM IN ATTIC

Comments: