CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20191614Address:1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Rated Assembly Inspection		Robb Popp	Partial	Monday, November 08, 2021	
Informational:					
1	THIRD FLOOR	-AREAS APPROVED-			
	ational: SECOND FLOOR	BUILDING C COMPLETE			
		BUILDING B COMPLETE			
Informat		BUILDING A COMPLETE EXCEPT ELEVA	TOR		
2		-AREAS APPROVED-			
		BUILDING C: COMPLETE			
		BUILDING B: COMPLETE			
		BUILDING A: COMPLETE EXCEPT AT ELE	VATOR		

Informational:

Informational:				
3	FIRST FLOOR	-AREAS APPROVED-		
		BUILDING C		
		COMPLETE		
		BUILDING B		
		COMPLETE		
		BUILDING A		
		COMPLETE		
		****MCAL BUILDING***		
		RM 165 NORTH WALL LAYER OVER SHAFT WALL		
		1057 WALLS FOR ELECTRICAL GEAR		
		RC OK ABOVE COOLER SCREW PATTERN AT WALLS AND CEILINGS FOR COOLER		
		RC IN CORRIDORS FIRST 16" FOR SOFFITS: CORRIDORS		
		167,176,177,177A,178A,169,172,173,39,42,31,34,48		
		PRE ROCK AT CORRIDOR SOFFITS: 176,177,177A		
		RC ROOMS 101-147, 181,182		
		RC CHANNEL ROOMS: 102-153,161-163		
		RC CORRIDORS 169,172,173,176,177a,177,48,39,42		
		-SCREW PATTERN UNITS 1-18, 1041-1044		
		-SCREW PATTERN CORRIDORS 160,169,172,173,176,177,177a walls		
		-RATED LAYER AT BATHROOM CEILINGS 101-145, 147		
		-SCREW PATTERN AT AT AL UNITS: 101-158, 161-163		
		-RC AT MC UNITS 1-18,21,24-33, 36,45,46		
		-RC SHARED SPACES 150-158, 162, 163,159,161,162A,170,171,179		
		-RATED LAYER AT BATHROOMS 1-18		
		-162 FIRST LAYER AT COLUMNS AND BEAMS, PRE ROCK FOR SOFFITS		
		-SECOND LAYER AT COLUMNS 163 NORTH AND SOUTH INSIDE WALLS OK		
		-RATED LAYER AT 149,154,171, 162 TO UNFINISHED COLUMN		
		-MCAL 2hr wall OK		
		-SOFFITS IN CORRIDORS 177A, 177,176, 34,39,42,		
		-SCREW PATTERN MC THROUGHOUT		
Corrective Action Required:				
4	Miscellaneous	-ADDRESS COLUMN RATING AT 162/163-SECOND LAYER REQUIRED AT WALL		
•	Correction	SIDES		
		-PROVIDE 5/8" GLASS MAT SHEATHING AT CANOPIES PER PLAN		

Comments: