

#### The Science You Build On.

### **Letter of Transmittal 1**

Client: Hy-Vee Construction	Project No:	B2100276
-----------------------------	-------------	----------

Project: Hy-Vee – Lee's Summit #2 Remodel

**Date:** February 26, 2021 Braun Intertec Corporation

Email:

11529 West 79th Street, Building 21

Lenexa, KS 66214

**To:** Jack Meyer Phone: (515) 419-5669

Hy-Vee Construction 5605 N.E. 22<sup>nd</sup> Street Des Moines, IA 50313

Re: Reports and Test Results

### Documents Sent Comments

Daily Reports January 21, 2021 – February 24, 2021

Compressive Strength of Concrete Reports Test Nos. 1-3

Copy List

### **Contact Information:**

Sent By: Carrie Keeling

Email: CKeeling@braunintertec.com

Phone:

Rev: 05/05/2014



11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909 Client: Project:

Hy-Vee Construction B2100276 5605 N.E. 22nd Street Hy-Vee - L

5605 N.E. 22nd Street Hy-Vee - Lee's Summit #2 Remodel
Des Moines, IA 50313 310 SW Ward Rd
Lees Summit, MO 64081

Activity Date: 01/21/2021 City of: Lee's Summit, MO Report Number: 1

Technician: Gelinne, Evan Braun Intertec PM: James Simmons Weather: Sunny 56

Coverage	Frequency	Notes
Soils	Periodic	
Concrete Construction	Continuous	
Special Cases	Continuous	

Architect/engineer authorized changes to approved plans?: No

#### Work Completed Description:

Installation of the drilled and epoxied rebar was observed for the footing at grid B-1.1 referencing plan page S1.0. Installation was observed with respect to hole size, depth and cleanliness, rebar size and spacing, and type of epoxy used.

Observed the bearing materials within the bases of the footing referenced above. The bearing materials consisted of the in situ soil and appeared stable.

Observed the reinforcing steel within the footing referenced above. Reinforcing steel was observed with respect to grade, size, spacing, lap splice length and clearance.

Observed the placement of concrete within the footing referenced above. Performed field tests and cast 1 set of 5 compressive strength test specimens.

#### **Tests Performed:**

Field soil bearing tests, field concrete tests, visual inspection

Outstanding discrepancies on this project?: No

Report discussed with and sent to contractor?: No

To the best of our knowledge, work inspected was done in accordance with the approved plans, specifications and applicable workmanship provisions of the current IBC, except as noted above.



### **Daily Field Notes**

11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909

Hy-Vee Construction 5605 N.E. 22nd Street Des Moines, IA 50313

Client:

B2100276 Hy-Vee - Lee's Summit #2 Remodel

310 SW Ward Rd Lees Summit, MO 64081

Project:

Activity Date: 01/22/2021 Temperature: 35

**PM:** James Simmons **Technician:** Gelinne, Evan

Report Number: 1
Weather: Sunny

Services Performed: Cylinder Pickup

### **Remarks / Comments**

Were all scheduled activities completed: Yes Were there any delays affecting our activities: No Report emailed to client or contractor: No

General Comments: Retrieved compressive strength test specimens cast on 01/21/2021.

James Simmons



11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909 Client: Project:

Hy-Vee Construction B2100276

5605 N.E. 22nd Street Hy-Vee - Lee's Summit #2 Remodel
Des Moines, IA 50313 310 SW Ward Rd
Lees Summit, MO 64081

Activity Date: 01/26/2021 City of: Lee's Summit, MO Report Number: 2

Technician: Gelinne, Evan Braun Intertec PM: James Simmons Weather: Cloudy 26

Coverage	Frequency	Notes
Concrete Construction	Continuous	
Special Cases	Periodic	

Architect/engineer authorized changes to approved plans?: No

#### **Work Completed Description:**

Observed the placement of reinforcing steel and grout within the structural masonry at grid 1.1-B referencing plan page S1.0 for reinforcement along both sides of the new doorway at 0' to 20' above finished floor. Grout was placed in lifts not exceeding 5'4" in elevation and consolidated via mechanical vibration

Installation of the drilled and epoxied rebar was observed within the slab on grade for the stoop located at grid 1.1-B referencing plan page \$1.0. Installation was observed with respect to hole size, depth and cleanliness, bar size and spacing, and type of epoxy used.

Observed the reinforcing steel within the stoop referenced above. Reinforcing steel was observed with respect to grade, size, spacing, lap splice length and clearance.

Observed the reinforcing dowels for the slab on grade within the sushi utility trench, market grill bar utility trench, and the kitchen utility trench. Per the structural plans the dowels should be epoxied but the contractor was not aware of this so they did not have epoxy onsite. It was approved by the structural engineer of record to not use epoxy for the dowels within the utility trenches scheduled to be poured but should be used for the remainder of the project. Installation of the dowels were observed with respect to hole size, depth and cleanliness, and dowel size and spacing.

Observed the placement of concrete within the slab on grade for the stoop and the within the utility trenches referenced above. Performed field tests and cast 2 sets of 5 compressive strength test specimens.

#### **Tests Performed:**

Field concrete tests, visual inspection

#### Outstanding discrepancies on this project?: No

Report discussed with and sent to contractor?: No

To the best of our knowledge, work inspected was done in accordance with the approved plans, specifications and applicable workmanship provisions of the current IBC, except as noted above.



### **Daily Field Notes**

11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909

Hy-Vee Construction 5605 N.E. 22nd Street Des Moines, IA 50313

Client:

Project:

B2100276 Hy-Vee - Lee's Summit #2 Remodel 310 SW Ward Rd Lees Summit, MO 64081

Activity Date: 01/27/2021 Temperature: 26

PM: James Simmons Technician: Gelinne, Evan Report Number: 2 Weather: Cloudy

Services Performed: Cylinder Pickup

### **Remarks / Comments**

Were all scheduled activities completed: Yes Were there any delays affecting our activities: No Report emailed to client or contractor: No

General Comments: Retrieved compressive strength test specimens cast on 01/26/2021.

James Simmons



11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909 Client: Project:

Hy-Vee Construction B2100276 5605 N.E. 22nd Street Hy-Vee - L

5605 N.E. 22nd Street Hy-Vee - Lee's Summit #2 Remodel
Des Moines, IA 50313 310 SW Ward Rd
Lees Summit, MO 64081

Activity Date: 02/01/2021 City of: Lee's Summit, MO Report Number: 3

Technician: Vazquez-Nevarez, Israel Braun Intertec PM: James Simmons Weather: Cloudy 30

Coverage	Frequency	Notes
Concrete Construction	Continuous	

Architect/engineer authorized changes to approved plans?: No

#### **Work Completed Description:**

Observed the reinforcing steel within the slab in fill at approximately Lines B to B.2 and 1.1 to 1.3. Reinforcing steel was observed with respect to grade, size, spacing, lap splice length and clearance.

Observed the reinforcing dowels for the slab in fill within location referenced above. Per the structural plans the dowels were epoxied. Installation of the dowels were inspected with respect to hole size, dowel size and spacing.

Observed the placement of concrete within the slab on grade for the slab in fill and the within the location referenced above.

#### **Tests Performed:**

Field concrete tests, visual inspection

Outstanding discrepancies on this project?: No

Report discussed with and sent to contractor?: No

To the best of our knowledge, work inspected was done in accordance with the approved plans, specifications and applicable workmanship provisions of the current IBC, except as noted above.



11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909 Client: Project:

Hy-Vee Construction B2100276 5605 N.E. 22nd Street Hy-Vee - L

5605 N.E. 22nd Street Hy-Vee - Lee's Summit #2 Remodel
Des Moines, IA 50313 310 SW Ward Rd
Lees Summit, MO 64081

Activity Date: 02/16/2021 City of: Lees Summit, MO Report Number: 4

Technician: Arndt, Chad Braun Intertec PM: James Simmons Weather: Partly Cloudy 17

Coverage	Frequency	Notes
Steel Construction	Periodic	

Architect/engineer authorized changes to approved plans?: No

#### **Work Completed Description:**

In progress welding inspection of 30 web reinforcement installations of double angles in joists in roof below new RTU installations at grid approximations of H.5 - 3, E - 3, H - 5, and G - 9 as shown on detail 5 of sheet S.5.1. All angles are currently unfinished as the required welding calls out 1/8" fillets at a minimum of 1 inch in length on both sides of the joint design.

Welders certifications will be reviewed during the next visit

**Tests Performed:** 

Visual of welding

Outstanding discrepancies on this project?: No

Report discussed with and sent to contractor?: No

**Attachments** 




11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909

Client:

Hy-Vee Construction 5605 N.E. 22nd Street Des Moines, IA 50313 Project:
B2100276
Hy-Vee - Lee's Summit #2 Remodel
310 SW Ward Rd

Lees Summit, MO 64081



Nearly all connections are in need of additional and necessary welding



11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909 Client: Project:

Hy-Vee Construction 5605 N.E. 22nd Street Des Moines, IA 50313 B2100276 Hy-Vee - Lee's Summit #2 Remodel 310 SW Ward Rd Lees Summit, MO 64081



Improper technique and lack of post cleaning is a concern along with angle melt through

To the best of our knowledge, work inspected was done in accordance with the approved plans, specifications and applicable workmanship provisions of the current IBC, except as noted above.



11529 W. 79th St, Building 21 Lenexa, KS 66214 Phone: 913-962-0909 Client: Project:

Hy-Vee Construction B2100276 5605 N.E. 22nd Street Hy-Vee - L

5605 N.E. 22nd Street Hy-Vee - Lee's Summit #2 Remodel
Des Moines, IA 50313 310 SW Ward Rd
Lees Summit, MO 64081

Activity Date: 02/24/2021 City of: Lees Summit, MO Report Number: 5

Technician: Arndt, Chad Braun Intertec PM: James Simmons Weather: Sunny 58

Coverage	Frequency	Notes
Steel Construction	Periodic	

Architect/engineer authorized changes to approved plans?: No

#### **Work Completed Description:**

Arrived onsite and met with Thomas Remus and Brenton Ewell for final welding inspection of 46 web reinforcement installations of double angles in joists supporting roof below new RTU installations at grid approximations of D - 4, H.5 - 3, E - 3, F-6, H - 5, and G - 9 as shown on detail 5 of sheet S.5.1. 1/8" fillet welding was acceptable according to size, length and profile.

All reinforcement was installed according to detail provided on Sheet S5.1 using (L2x2x3/16") ASTM A36 mild steel within 3 inches of panel points below new rooftop installation.

Welder certification was sent to the acting CWI at Braun Intertec by Brenton and was reviewed to be current as of the corresponding dates.

#### **Tests Performed:**

Visual of welding

Outstanding discrepancies on this project?: No

Report discussed with and sent to contractor?: No

To the best of our knowledge, work inspected was done in accordance with the approved plans, specifications and applicable workmanship provisions of the current IBC, except as noted above.



## **Compressive Strength of Concrete**

Test Method: ASTM C39

Technician:

Cast By:

**Date Cast:** 

Report Date: 2/23/2021 Sample: 358345

11529 W. 79th St, Building 21

Lenexa.

Set #:

Specimen Size:

Specimens In Set:

Phone: 913-962-0909

Client: Project:

Hy-Vee Construction B2100276

5605 N.E. 22nd Street Hy-Vee - Lee's Summit #2 Remodel

310 SW Ward Rd Des Moines, IA 50313 Lees Summit, MO 64081

> **Sample Details** Gelinne, Evan Batched: 02:15 CST Gelinne, Evan Sampled: 02:36 CST 02:40 CST 01/21/21 Cast:

Truck / Ticket #: 467 / 823234 Sampled From: Chute Truck Empty: 02:49 CST Contractor: **Placement Method:** Chute **Placement Time:** 34 (min)

Location

Placement Location: Other

4" X 8"

**Location Details:** Building exterior, footing, grid B-1.1 referencing plan page S1.0 Sample Location / Notes: Building exterior, footing, grid B-1.1 referencing plan page S1.0

**Batch Log Specifications** Geiger Ready Mix Mix Design: A4U5564V444 Strength: 3000 (psi) Supplier:

Air: Not Applicable - 3.0 (%) Plant: Lee's Summit, MO

Slump: 3 - 5 (in) On-Site Admixtures: None

**Field Measurements** 

Weather: Slump (in): 4-1/4 (ASTM C143) **Plastic Unit Weight:** 

Air Temperature (F): 56 Concrete Temp (F): 70 (ASTM C1064) Air Content:

> Load Volume: 4 (yd3)

# **Lab Test Results**

Testing La	ı <b>b:</b> Kansas C	ity, 11529 V	V. 79th St, Bu	uilding 21, Lenexa, K	S					
Specimen Number	Test Age Days	Test Date	Field / Lab Cure Days	Average Cylinder Diameter (in)	Cylinder Area (in²)	Max Load (lbs)	Strength (psi)	Fracture Type	Break Remark	Capping Method
1-1	7	01/28/21	1/6	4.00	12.57	55,060	4,380	2	1A	N
1-2	28	02/18/21	1 / 27	4.01	12.63	68,660	5,440	2	1C	N
1-3	28	02/18/21	1 / 27	4.00	12.57	69,400	5,520	2	1C	N
1-4	28	02/18/21	1 / 27	4.00	12.57	67,770	5,390	2	1C	N
1-5	56 H	03/18/21	1 / 55							


Test Age Average Strengths (psi): 7 Day - 4380, 28 Day - 5450

**Capping Methods** N: ASTM C1231, Unbonded Caps 1A: The test result is for informational purposes.

1C: The average result at this age meets or exceeds the specified compressive strength.

Tested By: Stephen Tanquary (1,2,3,4)

Checked In: 01/22/2021 (1,2,3,4,5)



James Simmons 02/23/2021



## **Compressive Strength of Concrete**

Test Method: ASTM C39

Report Date: 2/26/2021 Sample: 358935

11529 W. 79th St, Building 21

Lenexa,

Phone: 913-962-0909

Client: Project:

Hy-Vee Construction B2100276

5605 N.E. 22nd Street Hy-Vee - Lee's Summit #2 Remodel Des Moines, IA 50313 310 SW Ward Rd

13 310 SW Ward Rd Lees Summit, MO 64081

Sample Details

Set #: 2 Technician: Gelinne, Evan Batched: 09:09 CST Specimen Size: Cast By: Gelinne, Evan Sampled: 09:28 CST 4" X 8" **Date Cast:** Specimens In Set: 01/26/21 Cast: 09:38 CST Truck / Ticket #: 423 / 823465 Sampled From: Chute Truck Empty: 09:42 CST Contractor: **Placement Method:** Chute **Placement Time:** 33 (min)

Location

Placement Location: Other

Location Details: Building exterior, slab on grade for the stoop at grid 1.1-B referencing plan page S1.0

Sample Location / Notes: Building exterior, slab on grade for the stoop located at grid 1.1-B referencing plan page S1.0

 Batch Log
 Specifications

 Supplier:
 Geiger Ready Mix
 Mix Design:
 A4US564V444
 Strength:
 4000 (psi)

 Plant:
 Lee's Summit, MO
 Air:
 4.5 - 7.5 (%)

On-Site Admixtures: None Slump: 3 - 5 (in)

Field Measurements

Weather:CloudySlump (in):3-3/4 (ASTM C143)Plastic Unit Weight:Air Temperature (F):26Concrete Temp (F):68 (ASTM C1064)Air Content:5.0 (ASTM C231)

Load Volume: 2.5 (yd³)

Lab Test Results

Testing Lab: Kansas City, 11529 W. 79th St, Building 21, Lenexa, KS Cylinder Specimen Test Test Field / Lab Average Cylinder Max Load Strength Fracture Break Capping Number Age Days **Date Cure Days** Diameter (in) Area (in²) (lbs) (psi) Type Remark Method 02/02/21 4.00 12.57 61,180 4,870 2-1 1/6 5 1A 2-2 28 02/23/21 1 / 27 4.00 12.57 71.560 5.690 2 1B Ν

28 3.99 1B 2-3 02/23/21 1 / 27 12.50 73,320 5,870 3 Ν 1 / 27 4.00 12.57 72,980 5,810 1B 2-4 28 02/23/21 2 Ν 03/23/21 2-5 56 H 1 / 55

Test Age Average Strengths (psi): 7 Day - 4870, 28 Day - 5790


TA: The test result is for informational purposes.

N: ASTM C1231, Unbonded Caps

**1B:** The result meets or exceeds the specified compressive strength.

**Tested By:** Gerald Brokeshoulder (1,2,3,4)

Checked In: 01/27/2021 (1,2,3,4,5)



James Simmons 02/26/2021



## **Compressive Strength of Concrete**

Test Method: ASTM C39

Report Date: 2/26/2021 Sample: 358946

11529 W. 79th St, Building 21

Lenexa.

Phone: 913-962-0909

Client: Project:

Hy-Vee Construction B2100276

5605 N.E. 22nd Street Hy-Vee - Lee's Summit #2 Remodel 310 SW Ward Rd

Des Moines, IA 50313 Lees Summit, MO 64081

**Sample Details** 

Set #: 3 Technician: Gelinne, Evan Batched: 12:30 CST Specimen Size: Cast By: Gelinne, Evan Sampled: 13:02 CST 4" X 8" **Date Cast:** 01/26/21 Cast: Specimens In Set: 13:06 CST Truck / Ticket #: 307 / 823466 Sampled From: Chute Truck Empty: 13:42 CST Contractor: **Placement Method:** Buggy **Placement Time:** 72 (min)

Location

Placement Location: Building Interior - Slab on Grade

**Location Details:** Slab within the sushi utility trench, market grill bar utility trench, and the kitchen utility trench

Sample Location / Notes: Building interior, slab for the market grill bar utility trench

> **Specifications Batch Log**

Geiger Ready Mix Mix Design: P4US564V450 Strength: 4000 (psi) Supplier:

Air: Not Applicable - 3.0 (%) Plant: Lee's Summit, MO

Slump: 3 - 5 (in) On-Site Admixtures: None

**Field Measurements** 

Weather: Slump (in): 4-1/2 (ASTM C143) **Plastic Unit Weight:** Cloudy

Air Temperature (F): 25 Concrete Temp (F): 75 (ASTM C1064) Air Content:

> Load Volume: 10 (yd3)

### **Lab Test Results**

Testing La	ı <b>b:</b> Kansas C	ity, 11529 V	V. 79th St, Bu	uilding 21, Lenexa, K	S					
Specimen Number	Test Age Days	Test Date	Field / Lab Cure Days	Average Cylinder Diameter (in)	Cylinder Area (in²)	Max Load (lbs)	Strength (psi)	Fracture Type	Break Remark	Capping Method
3-1	7	02/02/21	1/6	4.00	12.57	65,510	5,210	2	1A	N
3-2	28	02/23/21	1 / 27	4.00	12.57	82,680	6,580	3	1B	N
3-3	28	02/23/21	1 / 27	4.00	12.57	82,360	6,550	3	1B	N
3-4	28	02/23/21	1 / 27	3.99	12.50	84,920	6,790	3	1B	N
3-5	56 H	03/23/21	1 / 55							


Test Age Average Strengths (psi): 7 Day - 5210, 28 Day - 6640

**Capping Methods** N: ASTM C1231, Unbonded Caps 1A: The test result is for informational purposes.

1B: The result meets or exceeds the specified compressive strength.

Tested By: Gerald Brokeshoulder (1,2,3,4)

Checked In: 01/27/2021 (1,2,3,4,5)



James Simmons 02/26/2021