

Inspection Summary

1 Misc

****REPAIR EROSION CONTROL AT REAR**

- Fb laundry and mud walls from roof **not done. Fb the double stud wall
- Install roof flashings for vents
- Complete installing electrical fireplace
- Fb basement wall from joist space;
Fb wall vertically every ten ft or less **staple in place insulation used as fire blocking material
- Protect shower vent at basement bathroom wall
- Steel column not fully underneath I beam at stair corner **just add a couple of studs

****OK TO INSULATE**

Comments: