CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211291

Address: 2316 SW CHASE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Robb Popp Not Ready Tuesday, February 08,

Residential 2022

Corrective Action Required:

1 Misc

Corrective Action Required:

Misc This house is not ready for all rough inspection. Items listed are only in the garage and list will change. Complete all items before further inspection

- -Maintain gravel filter, clean silt from street and storm inlet
- -Install PFH per detail at garage-nailing pattern, hold down straps, tension straps, anchor bolts etc.
- -Address holes drilled through LVL header at garage
- -Install anchor bolts within 12" of plate breaks and within 4" of end of plate in garage
- -Strap top plate lapped less than 24" at East garage
- -Address exterior walls not connected at top plates at garage/entry
- -Seal top and bottom plate penetrations in garage East wall and by entry
- -Attic access requires min 30" vertical clearance
- -Fur down and fireblock at hvac for Insulation in garage
- -Fur out at dryer box for insulation
- -Fireblock soffit line at fur down
- -Missing roof boots at radon and vent to roof
- -Support hip truss above single car bay-both locations
- -Address braced walls not nailed to top plates throughout

- -Nail exterior sheathing braced walls per plan throughout
- -Ceiling joists at garage tapered greater than 1/4 of depth of joist
- -Fireblock top of hvac chase
- -Nail ledger board for rafters to 2nd floor wall framing above garage and bath west side

Comments: