



LEE'S SUMMIT MISSOURI



FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

| | | | |
|---------------------|--|-----------|----------------|
| BUSINESS NAME | THE PRINCETON | | |
| ADDRESS | 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081 | | |
| OWNER/OPERATOR NAME | O'REILLY BUILD LLC: | TELEPHONE | (417) 862-9500 |
| ADDRESS | 5051 S NATIONAL AVE STE 4-110 SPRINGFIELD, MO 65810 Primary: (417) 862-9500 Cell: <NO CELL PHONE> | | |

EMERGENCY CONTACT INFORMATION

| | |
|----------|-----------|
| NAME | TELEPHONE |
| 1. _____ | |
| 2. _____ | |
| 3. _____ | |
| 4. _____ | |

LOSS REDUCTION TYPE

| | | | | | |
|------------------------------------|--|---------------------------------|--|---------------------------------------|--|
| <input type="checkbox"/> Occupancy | <input type="checkbox"/> Semi-Annual | <input type="checkbox"/> Annual | <input type="checkbox"/> Life Safety | <input type="checkbox"/> Sprinkler | <input type="checkbox"/> Hazardous Material Permit |
| <input type="checkbox"/> Complaint | <input type="checkbox"/> Explosive Storage | <input type="checkbox"/> UST | <input type="checkbox"/> Post-Incident | <input type="checkbox"/> Open Burning | <input type="checkbox"/> Other |
| CLASS: R-4 | Map#: 196K | PFA#: | KNOX BOX: | KNOX LOCATION: | PERMIT # |

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

| | | | |
|------------------------------|------------|---------|----------------------------|
| INSPECTION | INSPECTOR | OUTCOME | DATE |
| Alarm Test | Craig Hill | Partial | Tuesday, February 08, 2022 |
| Sprinkler - Hydrostatic Test | Craig Hill | Passed | Tuesday, January 04, 2022 |
| Sprinkler - Flow Test | Craig Hill | Partial | Tuesday, February 08, 2022 |

| | | | |
|---|------------|-----------|------------------------------|
| Sprinkler - Hydrostatic Test | Craig Hill | Partial | Thursday, October 14, 2021 |
| Alarm Test | Craig Hill | Partial | Wednesday, February 09, 2022 |
| Sprinkler - Flow Test | Craig Hill | Failed | Wednesday, February 09, 2022 |
| Corrective Action Required: 1 Label sprinkler room door. Label riser with area of protection. Dry system in memory care failed, need to re-test. Add wrench to spare head box. | | | |
| Alternate Protection Systems Inspection | Craig Hill | Not Ready | Wednesday, February 09, 2022 |

| | | | |
|-------------------|------------|--|-----------------------|
| DATE OF REPORT | INSPECTOR | PREVENTION FOLLOW-UP REQUIRED? | RESPONSIBLE SIGNATURE |
| February 09, 2022 | Craig Hill | <input type="checkbox"/> Yes <input type="checkbox"/> No | |