WATER UTILITIES LEE'S SUMMIT

1200 SE Hamblen Road | Lee's Summit, MO 64081 P: 816.969.1900 | F: 816.969.1935 backflow@cityofls.net | LSwater.net

Rackflow Provention Assembly Tost Data & Maintenance Penert

backnow Prevention Assembly lest Data & Maintenance Report					
New Mark Homes					
1916 SW River Run Dr., Lee's Summit, MO 64082					
Location of Backflow Assembly on Property Front Yard by water meter.					
Date of Test 10/29/21	Time AM PM P	Supply Pressure 80 LBS	Air Gap (2 x Supply Diamete Supply:IN. Gap: _	er)	PASS FAIL
Type of Assembly		Manufacturer	Model	Size	Serial Number
DCDA (Detector)	DC RP		350	1.0	AJC 4244
Height off Floor	Protection From		Supply Source		New Installation
FTIN	Freezing: Yes V No	Flooding: Yes V No	Public Potable Non-Potable V	Water Both Vater (e.g., LAKE)	✓ YES
Inital Test	ę	Passed Failed	Final Test After Repair		Passed Failed
Reduced Pressure Principle Assembly:			Reduced Pressure Principle Assembly:		
RELIEF VALVE opened at PSID (2 PSID or more)			RELIEF VALVE opened atPSID (2 PSID or more)		
2nd CHECK held backpressure			2nd CHECK held backpressure		
NO. 2 SHUTOFF VALVE leak tight			NO. 2 SHUTOFF VALVE leak tight		
1st CHECK held in direction of flowPSID (5 PSID or more)			1st CHECK held in direction of flow PSID (5 PSID or more)		
DIFFERENCE (1st check - relief) PSID (3 PSID or more)			DIFFERENCE (1st check - relief) PSID (3 PSID or more)		
			Note: Failure of any of the above items, requires repair.		
Initial Test Passed Pouble Check Valve Assembly: 1st CHECK held in direction of flow 2.2 PSID (1 PSID or more) 2nd CHECK held backpressure 2nd CHECK held in direction of flow 2.0 PSID (1 PSID or more) NO. 2 SHUTOFF VALVE leak tight Note: Failure of any of the above items, requires repair.			Final Test After Repair Double Check Valve Assembly: 1st CHECK held in direction of flowPSID (1 PSID or more) 2nd CHECK held backpressure/ 2nd CHECK held in direction of flowPSID (1 PSID or more) NO. 2 SHUTOFF VALVE leak tight Note: Failure of any of the above items, requires repair.		
Application:		Comments			
☐ Commercial ✓ Irrigation ☐ Fire Line ☐ Fire Line By-Pass **Meter # **Meter Read ☐ Point of Use					
The Above Report is Certified to be True, Accurate and Complete					
Tested By (Print) (Signature) JUAN O. VIDAL		Repaired by (Print)	(Signature)	Date of Repair	
JV LANDSCAPE SOLUTIONS LLC.			Final Test By (Print)	(Signature)	Date of Final Test
Missouri Certification Number Expiration Date		Owner or Owner's Representative Date			
33-2654 04/30/2022		10/29/21			
*If an existing PVB is beyond repair and needs replacement, it should be replaced by a DC or RP to meet current State and City regulations. New PVB installations or replacements are not permitted.					

**METER # and METER READ for the fire line by-pass meter on detector assemblies are required.

Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to report results of tests and inspections to the customer and water supplier.