

220 SE GREEN ST, LEE'S SUMMIT, MO 64064 PHONE: (816) 969-1930 FAX: (816) 969-1935 EMAIL: backflow@cityofls.net WEB: lswater.net

BACKFLOW PREVENTION ASSEMBLY TEST DATA AND MAINTENANCE REPORT

THE THE PARTY OF T			TEST DATA AND MAINTENANCE REPORT		
SERVICE ADDRESS					^
LOCATION OF BACKFLOW ASSEMBLY ON PROPERTY	Shaw	DR			
		•			•
DATE OF TEST TIME DATE	M. SUPPLY	PRESSURE	AIR GAP (2 X SUPPLY DIAMTER)		
TYPE OF ASSEMBLY MANUE ACTIONS	a. 85	LBS	larance	PASS [FAIL
DCDA (DETECTOR) RPDA (DETECTOR) PVB* (SEE BOTTOM OF FORM)		MODEL	SIZE SERIAL NUMBER		
PVB* (SEE BOTTOM OF FORM) HEIGHT OFF FLOOR PROTECTION FROM:		8	50 3/4 HF-135	(417)	
# FT _ IN FREEZING AYES [] NO FLOO	ODING Styr				TION
INITIAL TEST		FAILED	SUPPLY PUBLIC POTABLE WATER SOURCE: NON-POTABLE WATER (e.g., LAKE)	YES	☐ NO
REDUCED PRESSURE PRINCIPLE ASSEMBLY	(: \bar{\bar{\bar{\bar{\bar{\bar{\bar{	FAULED	FINAL TEST AFTER REPAIR REDUCED PRESSURE PRINCIPLE ASSEMBLY	PASSED	FAILE
PSID (2 PSID or more)		لــا	RELIEF VALVE		
- The table of more) [OPENED AT PSID (2 PSID or more)		
2ND CHECK held backpressure		П	2ND CHECK held backpressure		
NO. 2 SHUTOFF VALVE leak tight					
			NO. 2 SHUTOFF VALVE leak tight		
1ST CHECK held in direction of flow PSID (5 PSID or more)			1ST CHECK held in		
			direction of flow PSID (5 PSID or more)		
DIFFERENCE (1st check - relief) PSID (3 PSID or more)	_		DIFFERENCE		
			(1st check - relief)PSID (3 PSID or more)		
NOTE: Failure of any of the above items, require	es repair.		NOTE: Fallure of any of the above items, require	s repair.	ليوسا
INITIAL TEST DOUBLE CHECK VAVLE ASSEMBLY:	PASSED	FAILED	FINAL TEST AFTER REPAIR		
1ST CHECK held in	Z.		DOUBLE CHECK VAVLE ASSEMBLY:	PASSED	FAILED
direction of flow 2.8 PSID (1 PSID or more)			1ST CHECK held in		
			direction of flow PSID (1 PSID or more)		
2ND CHECK held backpressure	A		2ND CHECK held backpressure		F-3
END CHECK held in	* 140 - 1		·		
direction of flow 2.4 PSID (1 PSID or more)			2ND CHECK held in direction of flow PSID (1 PSID or more)	LJ	parag.
IO. 2 SHUTOFF VALVE leak tight	P4-		The state of the s	Ц	
OTE: Fallure of any of the above items, require	- Company		NO. 2 SHUTOFF VALVE leak tight		
PPLICATION: COMMENTE			NOTE: Failure of any of the above items, requires	repair.	
COMMERCIAL	5,01	anhel	low Worken Jene		
IRRIGATION		7			1
FIRE LINE					
FIRE LINE BY-PASS					
**METER #					
**METER READ					1
POINT OF USE					
E ABOVE REPORT IS CERTIFIED TO E	ETRUE	ACCUP	ATE-AND-COMPLETE		
ED DV	POBRE //	IRE	PAIRED BY CONTROL		
(PRINT)	1/2		(SIGNATURE)	DATE OF REI	PAIR
BUELS BETER LOUISIGNA	0	dera.	At Treste at a		100
RNIEL J PORTEN 1/ 0.18	JSn.	12	AL TEST BY (PRINT) (SIGNATURE)	DATE OF FIN	ALTEST
ene Valle Land	180ap	OW	NED OR CHAPTER PROPERTY (GIGINALINE)		
* If an existing PVB is beyond repair and needs re	2022 Placement,	it should be	NEP OR CHAIRMS OFFICE (SIGNATURE)		