

## FIRE DEPARTMENT

				NOTIFIC	ATIONS/CC	DNIACIINFORMA	AHO	N SECTION	
PAGE 1									
☐ CHANGES									
BUSINESS NAME	TH	IE PRINCETON	N						
ADDRESS	17	1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081							
OWNER/OPERATO	OR NAME	O'REILLY BUILD LLC: TELEPH					IE	(417) 862-9500	
ADDRESS	5051 S NATIONAL AVE STE SPRINGFIELD, MO 65810 Primary: (417) 862-9500 Cell: <no cell="" phone=""></no>								
			EMERGENC	Y CONTA	CT INFORM	IATION			
NAME					TE	ELEPHONE			
1.									
2.									
3.									
4.									
			LOS	S REDUC	TION TYPE				
☐ Occupancy	☐ Semi-A	nnual	☐ Annual	Life S	afety	Sprinkler		Hazardous Material Permit	
☐ Complaint	☐ Explos	ive Storage	☐ UST	☐ Post-	Incident	☐ Open Burning		Other	
CLASS: R-4	Ma 196		PFA#:	KNOX BO	X:	KNOX LOCATION:		PERMIT#	
	1100		LOSS R	EDUCTIO	N NARRATI	VE			
	TIONS NOT	FD		ſ		LATIONS RESOL\	/FD		
NO VIOLATIONS NOTED  Last Inspection 1st Inspection			2nd	Inspection	_	3rd Inspection 4th Inspection			
INSPECTION	PECTION INSP		ECTOR		OUTCOME	DATE			
Alarm Test Cra		Craig	g Hill		Partial	Tuesday	Tuesday, February 08, 2022		
Sprinkler - Hyd	drostatic Te	e <b>st</b> Craiç	g Hill		Passed	Tuesday	, Jar	nuary 04, 2022	
Sprinkler - Flow Test		Craig Hill		Partial		Tuesday	Tuesday, February 08, 2022		

Sprinkler - Hydrostatic Test	Craig Hill	Partial	Thursday, October 14, 2021			
Alarm Test	Craig Hill	Partial	Wednesday, February 09, 2022			
Sprinkler - Flow Test  Corrective Action Required:  1 Label sprinkler room de Label riser with area of Dry system in memory Add wrench to spare h	protection. care failed, need to re-test.	Failed	Wednesday, February 09, 2022			
Alternate Protection Systems Inspection	Craig Hill	Not Ready	Wednesday, February 09, 2022			
Alternate Protection Systems Inspection	Craig Hill	Passed	Monday, February 14, 2022			
Occupancy Inspection - Fire Craig Hill Failed Monday, February 14, 2022  Corrective Action Required: 1 2026 covered sprinkler head 3042 horn strobe hanging from the wall 1022 with a covered sprinkler head 1017 with a covered sprinkler head First floor north hallway fire door exit signs are covered North hallway exterior illumination does not work Sprinkler system needs to be tagged current.						
	ing from the wall prinkler head prinkler head y fire door exit signs are coverd Ilumination does not work	Failed ed	Thursday, February 17, 2022			
Occupancy Inspection - Fire Corrective Action Required: 1 2026 covered sprinkler 1022 with a covered sprinkler 1017 with a covered sprinkler	orinkler head	Failed	Friday, March 18, 2022			

First floor north hallway fire door exit signs are covered								
Occupand	cy Inspection - Fire	e Ben Hicks	Failed	Fr	riday, March 18, 2022			
-	Action Required: 2026 covered sprint 3042 horn strobe ha 1022 with a covered 1017 with a covered First floor north hall North hallway exter	kler head anging from the wall d sprinkler head	/ered					
Occupano	cy Inspection - Fire	Craig Hill	Failed	Fr	riday, March 25, 2022			
Corrective Action Required:  1 2026 covered sprinkler head 3042 horn strobe hanging from the wall 1022 with a covered sprinkler head 1017 with a covered sprinkler head First floor north hallway fire door exit signs are covered North hallway exterior illumination does not work Sprinkler system needs to be tagged current.								
Corrective 2	Action Required: Dry System needs t Spa smoke is cover	to be plumbed into the floor						
DATE OF RE	PORT	INSPECTOR	PREVENTION REQUIRED?	N FOLLOW-UP	RESPONSIBLE SIGNATURE			
March 25,	2022	Craig Hill	☐ Yes	□ No				
		· · · · · · · · · · · · · · · · · · ·						