

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213817

Address: 3746 SW MARYVILLE PL, LEES SUMMIT, MO 640823744 SW MARYVILLE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Patrick Schonfeldt	Failed	Wednesday, May 04, 2022

Corrective Action Required:

1	Misc	-No vents or ducts at roof deck within 4' of firewall -fire rock break away clips per plans -repair damaged sections of fire rock -fire rock required to be seated in H stud -rock required to seat in C channel at roof deck -see rock at master bed roof deck, rock is short of deck and can see daylight from next door unit, also rock is cut back from framing at front wall can see through to next door unit -seal firewall penetration SE cable basement
---	------	--

Comments: