CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213814

Address: 3821 SW MARYVILLE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Failed Thursday, May 12, 2022

Residential

Corrective Action Required:

1 Misc -No footing inspection performed, upload engineer report to portal

-provide stud shoe at 1st floor powder bath DWV

-address corner lap connection at front entry wall corner

-protect NM within 6' of attic access

-provide H2.5 clips dbl girder truss master bed

-support DWV every 48" oc

-unfinished basement wall receptacle required

-security blocking at basement door

-nail exterior sheathing at CS-PF bracing master bed windows, see detail in

plans or IRC R602.10.6.4 -gas line bond required

-UFER ground required per code

Comments: