#### CITY OF LEE'S SUMMIT

# Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

### **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20216206

Address: 109 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Thursday, May 26,

Residential 2022

Informational:

1 Misc \*\*5/24/22-2nd not ready

-Provide complete, approved, stamped plans

Corrective Action Required:

2 Miscellaneous Provide H2.5s covered patio Correction Provide H2.5s master shower

Provide 3 studs SE & NE corner rec room
Provide solid security blocking patio door
Fire block dwv at soffit & corner bed 6 closet

Fire block soffit at gas line bed 6

Connect bath exhaust with metallic tape bath 5

Provide mid point support vertical DWV 2" and smaller bath 5

Protect NM rec room at bath 5

Provide (2) 2x10 joist rec room per plan Nail exterior wall sheathing per code

Provide (2) 2x6 cedar support to ridge beam front porch per plan

Provide (4) stud pack girder truss bearing stair landing front door per plan

Strap top plate bed break within 24" bed 3 closet

Strap top plate bed 1 above window

Seal fire block fireplace bed 1
Strap top plate walk in closet bed 1
Seal top plate at furr out master shower

Connect exterior corner no overlap bed 2 Provide 3" SCH 40 column at foyer Sister continuous studs at stair landing & nail sheathing breaks per code Provide nut & washer at through bolt great room Provide solid blocking nail sheathing breaks stair landing Provide (3) stud pack at stair landing per plan Provide CS-PF bracing dining room Repair hole in floor flex room Provide hangers & nail off in flex room per plan Seal fire block dead space bath 4 Provide vent to roof kitchen sink Tighten anchor bolts garage Nail double joist together per code Address floor joist overbored for DWV 2nd car bay garage Provide full bearing for J12 girder truss at garage wall Provide stud pack for bearing at triple LVL garage entry Support gas flex line at flex room for 2nd floor fireplace Address (3) NM conductors through same bore kitchen (3) NM conductors staples together on stud

#### **Comments:**

Kitchen