CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20202637

Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Above Ceiling Inspection Robb Popp Partial Thursday, June 02,

2022

Corrective Action Required:

1 THE FOLLOWING 2 EAST EXTERIOR CANOPIES-OK
AREAS ARE NORTH EXTERIOR CANOPY-OK
APPROVED WEST EXTERIOR CANOPY OK

-CLEARSTORIES AT A,B,C

-SOFFITS AT: CLEAR STORY A100, B100A

-HARD LIDS AT A213, B114, 121A, B113, C100A

,,B115,B117,C101A,C10,C10A,C129,C127,C121,C115D,C102-C104, C208, C214,

C20

***BUILDING A: A111,A112,A113, A100A,A100C,,A13,A110B,A101, A103, A104, A105, A106 A108,A108A,A110,A110A,117A,117B,118,118B A202, 203, 204, 205, 207, 208, 209, 210,21,200A,23,24,220A

BUILDING B: 101-103, 105-108, 110, 110A, 111,112, 117,118, 121, 121C, 122, 201-206, 208, 209, 211, 212, 214A, 215, 216, 216A, CORRIDORS EXCEPT AT B10 AND AT RATED ASSEMBLIES

***B113,B115, B121C, B121D, B122, B121, B121B,121D,B120, B119 B212, B201, B203, B204-OK

***BUILDING C: 101,101A,106-109, 111-113, 119, 120, 122-126, 128-131, 201-204, 211, 212, ,115-115C, 217A-217D, 219-219C, ALL CORRIDORS EXCEPT AT RATED ASSEMBLIES

**C102, C104, C115A, C115B, C115C, C117, C118, C119, C210, C206, C207 OC216, C216B, OK FOR BORDERS ONLY

AREA D

- 1/27/22 HARD LIDS: D103 MEDIA CENTER, D101, D101, A la carte counter, G108D -

D102, D104, D105, D103, D107, D108, D109, D110, D13

AREA E:

-E114B, E115, E118, E117B

-E10 CORRIDOR HARD LID SOFFITS

Area E: E123, E124, E122, E101, E102, D103, E104, E105, E106, E107, E109, E109,

E10, E111, E112, E114A, E117A, E11A, E11B, E10

HARD LID OUTSIDE E123&124

AREA G: 102,103,106,107,108,108B,108F, G109, G108B, G108F, G108, G101, G10A-B, G11,

Corrective Action Required:

2 Misc

SEAL GAPS AT VESTIBULE SHAFT LAYER

Corrective Action Required:

3 Misc

3/11/22 - D110A OK

HARD LID OUTSIDE OF E123/E124 OK F104 RECALL WHEN GRID INSTALLED

B10/C10 CORRIDOR SET (2) SPRINKLER HEADS AT SOUTH END OF B10, LOOSE

MC ABOVE DISPLAY CASES, DRIVERS FOR LOW VOLT LIGHTING ON

BACKORDER, FIRECAULK PENETRATIONS AND ADDRESS GAP AT ROCK TO DECK

AT NORTH END OF C10 2 HOUR RATED ASSEMBLY, OTHER AREAS OK

Ι

Comments: