WATER UTILITIES LEE'S SUMMIT

1200 SE Hamblen Road | Lee's Summit, MO 64081 P: 816.969.1900 | F: 816.969.1935 backflow@cityofls.net | LSwater.net

Backflow Prevention Assembly Test Data & Maintenance Report

	on a too cimery	1001 2 4 14 4 14 14	miterialise itepoi	_
Trumark Home	S			
Service Address 516 David Ro	d			
Location of Backflow Assembly on Property				
Location of Backflow Assembly on Property	de of House			
Data of Tast	M Supply Pressure	Air Gap (2 x Supply Diameter)		-
6 00 0000 11 .00	м <u> 90</u> LBS	Supply: n/a IN. Gap: n/a IN	PASS FAI	L
Type of Assembly	Manufacturer	Model Size	Serial Number	10
✓ DC RP	Гороз	3/4	HF-35339	
DCDA (Detector) RPDA (Detector) PVB* (See Bottom of Form)	ector) Febco	850		
Height off Floor Protection From		Supply Source	New Installation	
	No Flooding: Yes No	Public Potable Water	□ Both □ □	
n/a _{FT} n/a _{IN} Freezing: Yes	No Flooding. Tes V No	Non-Potable Water (e.g.	, LAKE) YES NO	,
Inital Test	Passed Failed	Final Test After Repair	Passed Faile	ed
Reduced Pressure Principle Assembly:		Reduced Pressure Principle Asser	mbly:	
RELIEF VALVE opened atPSID (2 PSID or more)		RELIEF VALVE opened atPSID (2 PSID or more)		
2nd CHECK held backpressure		2nd CHECK held backpressure		
NO. 2 SHUTOFF VALVE leak tight		NO. 2 SHUTOFF VALVE leak tight		
1st CHECK held in direction of flow PSIE	(5 PSID or more)	1st CHECK held in direction of flow	VPSID (5 PSID or more)	1
DIFFERENCE (1st check - relief) PSID (3 PSID of	r more)	DIFFERENCE (1st check - relief)	PSID (3 PSID or more)	1
Note: Failure of any of the above items, requ	ires repair.	Note: Failure of any of the above	items, requires repair.	_
	B 1 F 1 - 1	F. 17 . 46 . D		
Initial Test Passed Failed Double Check Valve Assembly:		Final Test After Repair Passed Failed Double Check Valve Assembly:		
24		1st CHECK held in direction of flow PSID (1 PSID or more)		
		2nd CHECK held backpressure		
		2nd CHECK held in direction of flow PSID (1 PSID or more)		
NO. 2 SHUTOFF VALVE leak tight		NO. 2 SHUTOFF VALVE leak tight		
Note: Failure of any of the above items, requ	ires repair.	Note: Failure of any of the above	items, requires repair.	
Application:	Comments			
☐ Commercial	installed and test	ed backflow working corr	ectly	
✓ Irrigation				
Fire Line				
Fire Line By-Pass				
**Meter#				
**Meter Read				
Point of Use				
The Above Report is Certified to be True				
Tested By (Print) (Signatu	ire)	Repaired by (Print) (Signatur	re) Date of Repair	
Daniel J Coster				
				_
Company		Final Test By (Print) (Signatu	re) Date of Final Test	
Pine Valley Lawn & Landson	ape	Final Test By (Print) (Signatu	Date of Final Test	
Pine Valley Lawn & Landson Missouri Certification Number	Expiration Date	Final Test By (Print) (Signatu Owner or Owner's Representative	Date of Final Test	
Pine Valley Lawn & Landson	Expiration Date 9-30-2022	Owner or Owner's Representative	Date	

*If an existing PVB is beyond repair and needs replacement, it should be replaced by a DC or RP to meet current State and City regulations.

New PVB installations or replacements are not permitted.

**METER # and METER READ for the fire line by-pass meter on detector assemblies are required.

Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to report results of tests and inspections to the customer and water supplier.