WATER UTILITIES LEE'S SUMMIT

1200 SE Hamblen Road | Lee's Summit, MO 64081 P: 816.969.1900 | F: 816.969.1935 backflow@cityofls.net | LSwater.net

Backflow Prevention Assembly Test Data & Maintenance

Customer Trumark Ho	omes					
Service Address 1217 NE	Goshei	n Dr				
Location of Backflow Assembly on Proper	rty O' I	C 1 1				
	Side o	t House				
Date of Test Time		ipply Pressure	Air Gap (2 x Supply Diam	neter)		
6-23-2022 1 :	00 PM	90	LBS Supply: n/a IN. Ga		PASS FAIL	
	RP	anufacturer	Model	Size 3/4	Serial Number HF-34228	
DCDA (Detector) R PVB* (See Bottom of Form)	RPDA (Detector)	ebco	850		01220	
Height off Floor Protection F	From		Supply Source		Mous In stallation	
n/aIN Freezing:	Yes No Fi	ooding: Yes 🗸 N	Public Pota	ble Water Both e Water (e.g., LAKE)	New Installation YES NO	
Inital Test		Passed Fai	ed Final Test After Rep	air	Passed Faile	
Reduced Pressure Principle Assembly:			Reduced Pressure Prin	Reduced Pressure Principle Assembly:		
RELIEF VALVE opened atPSID (2 PSID or more)			RELIEF VALVE opened	RELIEF VALVE opened atPSID (2 PSID or more)		
2nd CHECK held backpressure			2nd CHECK held backp	2nd CHECK held backpressure		
NO. 2 SHUTOFF VALVE leak tight				NO. 2 SHUTOFF VALVE leak tight		
1st CHECK held in direction of flow PSID (5 PSID or more)			1st CHECK held in dire	1st CHECK held in direction of flowPSID (5 PSID or more)		
DIFFERENCE (1st check - relief) PSID (3 PSID or more)			DIFFERENCE (1st check -	DIFFERENCE (1st check - relief)PSID (3 PSID or more)		
Note: Failure of any of the above iter	ms, requires repai	r.	Note: Failure of any of	the above items, requires	repair.	
Initial Test Double Check Valve Assembly:		Passed Fail	ed Final Test After Repa		Passed Failed	
1st CHECK held in direction of flow 2.6 PSID (1 PSID or more)					(Dor more)	
2nd CHECK held backpressure						
2nd CHECK held in direction of flow 2.8 PSID (1 PSID or more)			2nd CHECK held in dire		SID or more)	
NO. 2 SHUTOFF VALVE leak tight						
Note: Failure of any of the above iter	ns, requires repai			the above items, requires i	repair.	
Application:	Cor	nments			- CPuill	
Commercial			sted backflow work	ing correctly		
✓ Irrigation				g co.iicoliy		
Fire Line						
Fire Line By-Pass						
**Meter#						
**Meter Read						
Point of Use						
The Above Report is Certified to b	A True Accurate	and Commission				
Tested By (Print)	(Signature)	and Complete	Descised (Dist)			
Daniel J Coster		Repaired by (Print)	(Signature)	Date of Repair		
Company			Final Test By (Print)	(Signature)	Date of Final Test	
	ndecana				Date of Fillal lest	
Pine Valley Lawn & La		Franks S			Date of Final Test	
Company Pine Valley Lawn & Lai Missouri Certification Number 34-11206		Expiration Date	Owner or Owner's Represe	entative	Date Of Final less	

Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to report results of tests and inspections to the customer and water supplier.