

FIRE DEPARTMENT

PAGE 1			NOTIFICATIONS/	CONTACT INFORMA	ATION	N SECTION
☐ CHANGES						
BUSINESS NAME	East Trails Middle	e School				
ADDRESS	1001 SE BAIL	EY RD, LEES	S SUMMIT, MO 640	081		
OWNER/OPERATOR NAME	MCCOWN G	ORDON CON	NSTRUCTION LLC:	TELEPHON	E (8	816) 960-1111
ADDRESS	850 MAIN ST KANSAS CIT Primary: (816 Cell: (816) 40	Y, MO 64105 5) 960-1111	5			
		EMERGENC	Y CONTACT INFO	RMATION		
NAME				TELEPHONE		
1						
2						
3.						
4.						
		LOS	S REDUCTION TYP	PE		
☐ Occupancy ☐ Sen	ni-Annual	☐ Annual	☐ Life Safety	Sprinkler		Hazardous Material Permit
☐ Complaint ☐ Exp	losive Storage	UST	☐ Post-Incident	Open Burning		Other
CLASS:	Мар#:	PFA#:	KNOX BOX:	KNOX LOCATION:		PERMIT#
		LOSS R	EDUCTION NARRA	ATIVE		
☐ NO VIOLATIONS N	IOTED		□ ALL V	IOLATIONS RESOLV	/FD	
	1st Inspection	2nd	Inspection	3rd Inspection		th Inspection
INSPECTION	INSPI	ECTOR	OUTCON	ME DATE		
Alarm Test	Craig		Partial	Friday, M	1ay 20	0, 2022
Change horn North East Fi	be to AV classr strobe above F	DC. r was not hoo	ked up to the syster in the system.	m.		

Sprinkler - Hydrostatic Test
Corrective Action Required: 1
Corrective Action Required: 2nd Floor C Building and 1st Floor C & D Building Passed Sprinkler - Hydrostatic Test
Alarm Test Craig Hill Failed Friday, July 15, 2022 Corrective Action Required: 1 Science Rooms The emergency gas shutoff for these rooms were not tested, as they were not ready. Each of these rooms is required to have a fire blanket. Pre-Final Walk Through 1. North side West emergency egress light was not operational 2. East side North emergency egress light was not operational 3. Main entrance emergency egress light was not operational 4. South music room emergency egress light was not operational. Alarm Test 1. All fire doors need to be tested again.
Corrective Action Required: Science Rooms The emergency gas shutoff for these rooms were not tested, as they were not ready. Each of these rooms is required to have a fire blanket. Pre-Final Walk Through North side West emergency egress light was not operational East side North emergency egress light was not operational Main entrance emergency egress light was not operational South music room emergency egress light was not operational. Alarm Test All fire doors need to be tested again.
Pre-Final Walk Through 1. North side West emergency egress light was not operational 2. East side North emergency egress light was not operational 3. Main entrance emergency egress light was not operational 4. South music room emergency egress light was not operational. Alarm Test 1. All fire doors need to be tested again.
All fire doors need to be tested again.
2. Cool down rooms still need to be tested.3. Everything South of the South 2hr fire wall needs to be tested again.
Water flow. 1. Label sprinkler room door 2. Install sprinkler spar head box with heads and wrench
Sprinkler - Flow Test Craig Hill Passed Friday, July 15, 2022
DATE OF REPORT INSPECTOR PREVENTION FOLLOW-UP REQUIRED? RESPONSIBLE SIGNATURE
July 15, 2022 Craig Hill Yes No