CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | | Inspector: | Outcome: | Date: |
|---------------------------|-------------------------------------|---------------------|--|-------------------------|
| Rated Assembly Inspection | | Robb Popp | Partial | Friday, August 05, 2022 |
| Correctiv 1 | e Action Required: THIRD FLOOR | | | |
| | | | ND CORRIDOR TO ARRA B N CORRIDOR LID TO UNIT 30 ETE AT UNITS AND CORRIDO | |
| | | | IG ABOVE HARD LID AT 3010 S IN SHAFT ASSEMBLY AT BL | |
| | | -RC CHANNEL AT 3001 | ND CORRIDOR EXCEPT AS NO NDING ENGINEERED LETTER 'S | |
| Correctiv 2 | e Action Required: STAIR TOWER 1 | : STAIRWAY 1 # 2003 | | |

| Corrective Action Required:3STAIR TOWER 2Corrective Action Required:4SECOND FLOOR | : STAIRWAY 2 # 2009 AREA A THE FOLLOWING AREAS ARE APPROVED |
|---|---|
| | **AREA A** -RC CHANNEL AT UNITS AND CORRIDOR TO AREA B -SCREW PATTERN AT CORRIDOR LID -SCREW PATTERN AT UNITS AND CORRIDOR COMPLETE EXCEPT AS NOTED BELOW -RC AT ACTIVITIES 2002 -RC AT 2001 -RC AT SUN ROOMS |
| | COMPLETE RATED ASSEMBLY AT CEILINGS ABOVE HARD LIDS IN 2004-2006, 2008, 2010 ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN CORRIDOR -RC AT UNITS |
| Corrective Action Required: 5 FOURTH FLOOR | : THE FOLLOWING AREAS ARE APPROVED : |
| | **AREA A** -RC CHANNEL CORRIDOR CEILING TO FIRE DOORS - -RC CHANNEL AT UNITS: 4004-4006, 4008,4021-4025,4027,4029 - AREA A SCREW PATTERN CORRIDOR CEILING TO FIRE DOORS - -RC CHANNEL Corridor 4007 walls from mechanical closet 4021 to lobby 4011 -SCREW PATTERN AT UNITS: 4021-4023, 4025, 4027, 4029, CORRIDOR 4007 to LOBBIES 4001,4011 -RC AT SUN ROOMS ALL UNITS COMPLETE ROCK AT STAIRWELL 2 |
| | ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN CORRIDOR |
| | 4006-Address rock at emt 4004,4005-incomplete COMPLETE RATED ASSEMBLY AT CEILINGS ABOVE HARD LIDS IN 4004-4006, 4008, 4010 |
| | ***AREA "B" *** -RC AT CORRIDOR 4017 AND LOBBY 4011 CEILINGS: -SCREW PATTERN AT UNITS AND CORRIDORS APPROVED -RC AT 4001 |
| Corrective Action Required: 6 FIFTH FLOOR | :THE FOLLOWING AREAS ARE APPROVED: |

AREA "A"

-RC CHANNEL AT CORRIDOR CEILINGS TO AREA "B"

-RC CHANNEL AT UNITS 5004-5006,5008,5021-5025,5027,5029

-RC CHANNEL AT CORRIDOR Walls from mechanical closet 5021 to lobby 5011

-SCREW PATTERN AT WALLS AND CEILINGS CORRIDOR 5007

-RC AT SUN ROOMS ALL UNITS

--ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN CORRIDOR

AREA "B" -RC AT CORRIDOR 5017 APPROVED -LOBBY 5011- RC AT CEILING -SCREW PATTERN AT WALLS AND CEILINGS CORRIDOR 5007 -RC AT UNITS AND CORRIDORS -RC AT 5001

Corrective Action Required:

7 Misc

Comments: