CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Friday, August 19, 2022
Corrective Action Required: 1 THIRD FLOOR		: THE FOLLOWING AREAS A	ARE APPROVED :	
			ND CORRIDOR TO ARRA B N CORRIDOR LID TO UNIT 30 ETE AT UNITS AND CORRIDO	
		COMPLETE RATED CEILING ABOVE HARD LID AT 3010,3008,3004-3006 ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS CORRIDOR		
		-RC CHANNEL AT 3001	ND CORRIDOR EXCEPT AS NO NDING ENGINEERED LETTER	
Correctiv 2	e Action Required: STAIR TOWER 1	: STAIRWAY 1 # 2003	3 AND CORRIDORS	

-RC AT CEILING

		-RC AT CEILING
Correctiv	ve Action Required:	
3	STAIR TOWER 2	: STAIRWAY 2 # 2009 AREA A
		-RC AT CEILINGS
		*ADDRESS RATING NOT EXTENDED TO ROOF DECK
Correctiv	ve Action Required:	
4	SECOND FLOOR	THE FOLLOWING AREAS ARE APPROVED
		AREA A
		-RC CHANNEL AT UNITS AND CORRIDOR TO AREA B
		-SCREW PATTERN AT CORRIDOR LID
		-SCREW PATTERN AT UNITS AND CORRIDOR COMPLETE EXCEPT AS NOTED
		BELOW
		-RC AT ACTIVITIES 2002
		-RC AT 2001
		-RC AT SUN ROOMS
		COMPLETE RATED ASSEMBLY AT CEILINGS ABOVE HARD LIDS IN 2004-2006,
		2008, 2010
		ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN
		CORRIDOR
		-RC AT UNITS
		-RCATONITS
		AREA B
		-RC AT UNITS AND CORRIDORS PENDING ENGINEERED LETTER FOR LEDGER
		CONNECTION AT ELEVATOR WALL
Correctiv	ve Action Required:	
5	FOURTH FLOOR	: THE FOLLOWING AREAS ARE APPROVED :
5		
		AREA A
		-RC CHANNEL CORRIDOR CEILING TO FIRE DOORS -
		-RC CHANNEL AT UNITS: 4004-4006, 4008,4021-4025,4027,4029
		- AREA A SCREW PATTERN CORRIDOR CEILING TO FIRE DOORS -
		-RC CHANNEL Corridor 4007 walls from mechanical closet 4021 to lobby 4011
		-SCREW PATTERN AT UNITS: 4021-4023, 4025, 4027, 4029, CORRIDOR 4007 to
		LOBBIES 4001,4011
		-RC AT SUN ROOMS ALL UNITS
		-RCATSON ROOMS ALL UNITS
		—-COMPLETE ROCK AT STAIRWELL 2
		ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN
		CORRIDOR
		4006-Address rock at emt
		4004,4005-incomplete
		COMPLETE RATED ASSEMBLY AT CEILINGS ABOVE HARD LIDS IN 4004-4006,
		4008, 4010
		***AREA "B" ***
		***AREA "B" *** -RC AT CORRIDOR 4017 AND LOBBY 4011 CEILINGS:

		-SCREW PATTERN AT UNITS AND CORRIDORS APPROVED
Corroctiv	e Action Required:	-RC AT 4001
6	FIFTH FLOOR	:THE FOLLOWING AREAS ARE APPROVED:
		AREA "A"
		-RC CHANNEL AT CORRIDOR CEILINGS TO AREA "B"
		-RC CHANNEL AT UNITS 5004-5006,5008,5021-5025,5027,5029
		-RC CHANNEL AT CORRIDOR Walls from mechanical closet 5021 to lobby 5011 -SCREW PATTERN AT WALLS AND CEILINGS CORRIDOR 5007
		-RC AT SUN ROOMS ALL UNITS
		-SCREW PATTERN AT SUN ROOMS EXCEPT AS NOTED
		ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN CORRIDOR
		AREA "B"
		-RC AT CORRIDOR 5017 APPROVED
		-LOBBY 5011- RC AT CEILING
		-SCREW PATTERN AT WALLS AND CEILINGS CORRIDOR 5007
		-RC AT UNITS AND CORRIDORS
		-RC AT 5001
- ··		-SCREW PATTERN AT UNITS AND CORRIDOR EXCEPT AS NOTED
Corrective Action Required:		
7	Misc	-Provide missing dampers at ceilings throughout area B
Compating	A ati a a Da avvina du	-Patch rock and support RC in sunroom 4021
Corrective Action Required:		
8	STAIR TOWER 3	*ADDRESS RATING NOT EXTENDED TO DECK -MISSING h2.5s at hip trusses

Comments: