

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20210263

Address: 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	Robb Popp	Partial	Thursday, August 25, 2022

Corrective Action Required:

1	Miscellaneous Correction	Stairwells OK
---	--------------------------	---------------

Corrective Action Required:

2	SECOND FLOOR	: THE FOLLOWING AREAS ARE APPROVED :
---	--------------	--------------------------------------

- 2ND FLOOR AREA A  
- UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2005,2006  
-2002 ACTIVITIES - OK

2001- seal gaps dead spaces, fireblock ceiling line at existing tie in doorway

AREA B:

2011-OK  
2015,2016,2019-OK

2026-seal conduit penetration in bed 2 closet, complete fur out and fireblocking at storm in bed 1,

2031-OK  
2028-OK  
2033-OK

2030- -OK  
2035-OK

2001-INSTALL MISSING FIRE DAMPERS

Corrective Action Required:  
3 THIRD FLOOR

: THE FOLLOWING AREAS ARE APPROVED :

:: 3ND FLOOR AREA A :  
3004,3005,3006,3021,3022,2023,3024,3025,3027, 302

3001- Seal gaps in fireblocking

:::AREA B-  
3035- complete bath exhaust, midpoint strap dwv in bath, complete  
mechanical in back bed  
3030-complete bath exhaust and mechanical in back bed  
3033-ok  
3028-ok  
3031-OK  
3026-ok  
3011-address ledger connections at elevator,  
3001- INSTALL MISSING FIRE DAMPERS

Corrective Action Required:  
4 FOURTH FLOOR

THE FOLLOWING AREAS ARE APPROVED

:::AREA A:  
4004-4006,4021-4025,4027,402,  
4001 - Seal gaps in Fireblocking

AREA "B"  
4011-OK  
4035-OK  
4030-OK  
4033 OK  
4028-OK  
4031-address main lugs at panel, joist hangers at deck tension tie joist  
4026-OK  
4001-INSTALL MISSING FIRE DAMPERS

Corrective Action Required:  
5 FIFTH FLOOR

AREA "A"  
THE FOLLOWING AREAS ARE APPROVED:  
5004-5006,5021-5025,5027,5029

5001-INSTALL MISSING FIRE DAMPERS

AREA "B"  
-5035-OK  
-5030-OK  
5033-OK  
5028-OK  
5031-OK  
5026-OK

**Comments:**