## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Rated Assembly Inspection	Robb Popp	Partial	Monday, August 29, 2022	
Corrective Action Required: 1 THIRD FLOOR	: THE FOLLOWING A	REAS ARE APPROVED :		
	-SCREW PATTERN P	IITS AND CORRIDOR TO A ATTERN CORRIDOR LID TO OMPLETE AT UNITS AND C		
	COMPLETE RATED CEILING ABOVE HARD LID AT 3010,3008,3004-3006 ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN CORRIDOR			
	-RC CHANNEL AT 30 **3011- RC APPROV ELEVATOR	IITS AND CORRIDOR EXCE 01 ED PENDING ENGINEEREE T UNITS AND CORRIDORS		
Corrective Action Required:				

2	STAIR TOWER 1	: STAIRWAY 1 # 2003 -RC AT CEILING -SCREW PATTERN WALLS AND CEILING
Correctiv	e Action Required:	-SCREW FATTERN WALLS AND CLIEING
3	STAIR TOWER 2	: STAIRWAY 2 # 2009 AREA A
5	STAIL TOWER 2	-RC AT CEILINGS
		-FIRST LAYER AT CEILING AND TOP OUT WALLS
Correctiv	e Action Required	
4 SECOND FLOOP	SECOND FLOOR	THE FOLLOWING AREAS ARE APPROVED
		**AREA A**
		-RC CHANNEL AT UNITS AND CORRIDOR TO AREA B
		-SCREW PATTERN AT CORRIDOR LID
		-SCREW PATTERN AT UNITS AND CORRIDOR COMPLETE EXCEPT AS NOTED BELOW
		-RC AT ACTIVITIES 2002 -RC AT 2001
		-RC AT SUN ROOMS
		COMPLETE RATED ASSEMBLY AT CEILINGS ABOVE HARD LIDS IN 2004-2006,
		2008, 2010
	ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN	
		CORRIDOR -RC AT UNITS
		-RCATONIIS
		**AREA B**
		-RC AT UNITS AND CORRIDORS PENDING ENGINEERED LETTER FOR LEDGER
		CONNECTION AT ELEVATOR WALL
		-SCREW PATTERN AT UNITS AND CORRIDOR
Correctiv	e Action Required:	
5	FOURTH FLOOR	: THE FOLLOWING AREAS ARE APPROVED :
		**AREA A**
		-RC CHANNEL CORRIDOR CEILING TO FIRE DOORS -
		-RC CHANNEL AT UNITS: 4004-4006, 4008,4021-4025,4027,4029
		- AREA A SCREW PATTERN CORRIDOR CEILING TO FIRE DOORS -
		-RC CHANNEL Corridor 4007 walls from mechanical closet 4021 to lobby 4011
		-SCREW PATTERN AT UNITS: 4021-4023, 4025, 4027, 4029, CORRIDOR 4007 to
		LOBBIES 4001,4011
		-RC AT SUN ROOMS ALL UNITS
		—-COMPLETE ROCK AT STAIRWELL 2
		ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN
		CORRIDOR
		4006-Address rock at emt
		4004,4005-incomplete
		COMPLETE RATED ASSEMBLY AT CEILINGS ABOVE HARD LIDS IN 4004-4006, 4008, 4010

Corrective Action Required:	***AREA "B" *** -RC AT CORRIDOR 4017 AND LOBBY 4011 CEILINGS: -SCREW PATTERN AT UNITS AND CORRIDORS APPROVED -RC AT 4001		
6 FIFTH FLOOR	:THE FOLLOWING AREAS ARE APPROVED:		
	<ul> <li>**AREA "A"**</li> <li>-RC CHANNEL AT CORRIDOR CEILINGS TO AREA "B"</li> <li>-RC CHANNEL AT UNITS 5004-5006,5008,5021-5025,5027,5029</li> <li>-RC CHANNEL AT CORRIDOR Walls from mechanical closet 5021 to lobby 5011</li> <li>-SCREW PATTERN AT WALLS AND CEILINGS CORRIDOR 5007</li> <li>-RC AT SUN ROOMS ALL UNITS</li> <li>-SCREW PATTERN AT SUN ROOMS EXCEPT AS NOTED</li> <li>ADDRESS PENETRATIONS IN SHAFT ASSEMBLY AT BUILDING SEPARATIONS IN CORRIDOR</li> </ul>		
	***AREA "B"*** -RC AT CORRIDOR 5017 APPROVED -LOBBY 5011- RC AT CEILING -SCREW PATTERN AT WALLS AND CEILINGS CORRIDOR 5007 -RC AT UNITS AND CORRIDORS -RC AT 5001 -SCREW PATTERN AT UNITS AND CORRIDOR EXCEPT AS NOTED		
Corrective Action Required: 7 Misc Corrective Action Required:	-Provide missing dampers at ceilings throughout area B		
8 STAIR TOWER 3	RC CHANNEL AT CEILING -FIRST LAYER AT CEILING AND TOP OUT WALLS		

Comments: