## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Commercial Corrective Action Required: 1 Miscellaneous Correction		Inspector:	Outcome:	Date:		
		Robb Popp	Partial	Monday, October 03, 2022		
		Stairwells OK				
Corrective 2	e Action Required: SECOND FLOOR	: THE FOLLOWING ARI	EAS ARE APPROVED :			
		- 2ND FLOOR AREA A - UNITS 2021,2022,202	2ND FLOOR AREA A UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2006,2001			
		AREA B:				
			2019,2028-2030,2035-Ok It and fireblocking at sto G FIRE DAMPERS			
		2005-Access panels				
Corrective Action Required:		2002-Access panels to	or dampers, seal penetra	ations		
3	THIRD FLOOR	: THE FOLLOWING ARI	EAS ARE APPROVED :			
		:: 3ND FLOOR AREA A 3004,3005,3006,3021,3	: 3022,2023,3024,3025,302	27, 3002,3001,3013		

		:::AREA B- 3035-COMPLETE MECHANICAL 3030-COMPLETE MECHANICAL 3026,3031,3028,3033,3008,3010-ok
Corrective	e Action Required: FOURTH FLOOR	3011-address ledger connections at elevator, 3001- INSTALL MISSING FIRE DAMPERS
4		THE FOLLOWING AREAS ARE APPROVED
		::AREA A: 4004-4006,4021-4025,4027,4002,4001,4013
		AREA "B" 4008,4010,4011,4026,4028,4033,4030,4035-OK 4031-address main lugs at panel, joist hangers at deck tension tie joist 4001-INSTALL MISSING FIRE DAMPERS 4005-Provide access panels for j boxes in ceiling 4006-Seal penetrations
Corrective 5	e Action Required: FIFTH FLOOR	AREA "A" THE FOLLOWING AREAS ARE APPROVED: 5004-5006,5021-5025,5027,5029 5013-Complete fresh air duct through ceiling, provide dampers 5001-INSTALL MISSING FIRE DAMPERS
		AREA "B" 5033,5028,5026, 5031,5035,5030,5010,5007 5004-Provide dampers at ceilng 5005-Access panels and cover plates above ceiling 5006-Seal gaps at dampers

**Comments:**