CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Commercial		Inspector:	Outcome:	Date:
		Robb Popp	Partial	Tuesday, October 04, 2022
Correctiv 1	e Action Required: Miscellaneous Correction	Stairwells OK		
Corrective 2	e Action Required: SECOND FLOOR	: THE FOLLOWING AREA	S ARE APPROVED :	
		- 2ND FLOOR AREA A - UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2006,2001		
		AREA B:		
		2011,2013, 2015,2016,20 2026, complete fur out a 2001-INSTALL MISSING F	and fireblocking at storm in	bed 1,
		2005-Access panels	lampers, seal penetrations	
Correctiv	e Action Required:		ampero, sear perietrations	
3	THIRD FLOOR	: THE FOLLOWING AREA	S ARE APPROVED :	
		:: 3ND FLOOR AREA A : 3004,3005,3006,3021,302	22,2023,3024,3025,3027, 300	2,3001,3013

		:::AREA B- 3026,3031,3028,3033,3008,3010, 3030, 3035-ok		
Correctiv	ve Action Required: FOURTH FLOOR	3011-address ledger connections at elevator, 3001- INSTALL MISSING FIRE DAMPERS		
4		THE FOLLOWING AREAS ARE APPROVED		
		::AREA A: 4004-4006,4021-4025,4027,4002,4001,4013		
		AREA "B" 4008,4010,4011,4026,4028,4033,4030,4035-OK		
		4031-address main lugs at panel, joist hangers at deck tension tie joist 4001-INSTALL MISSING FIRE DAMPERS		
		4005-Provide access panels for j boxes in ceiling 4006-Seal penetrations		
Corrective Action Required:				
5	FIFTH FLOOR	AREA "A"		
		THE FOLLOWING AREAS ARE APPROVED:		
		5004-5006,5021-5025,5027,5029		
		5013-Complete fresh air duct through ceiling, provide dampers 5001-INSTALL MISSING FIRE DAMPERS		
		SUUL-INSTALL MISSING FIRE DAMPERS		
		AREA "B" 5033,5028,5026, 5031,5035,5030,5010,5007 5004-Provide dampers at ceilng 5005-Access panels and cover plates above ceiling 5006-Seal gaps at dampers		

Comments: