CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210263

Address: 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Robb Popp Partial Tuesday, October 11,

Commercial 2022

Corrective Action Required:

1 Miscellaneous Stairwells OK
Correction ***GARAGE LEVEL-

LOBBY 1002 FRAMING OK

Corrective Action Required:

2 SECOND FLOOR : THE FOLLOWING AREAS ARE APPROVED :

- 2ND FLOOR AREA A

- UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2006,2001

AREA B:

2011,2013, 2015,2016,2019,2028-2030,2035-OK

2026, complete fur out and fireblocking at storm in bed 1,

2001-INSTALL MISSING FIRE DAMPERS

2005-Access panels

2002-Access panels for dampers, seal penetrations

Corrective Action Required:

3 THIRD FLOOR : THE FOLLOWING AREAS ARE APPROVED :

:: 3ND FLOOR AREA A:

3004,3005,3006,3021,3022,2023,3024,3025,3027,3002,3001,3013

:::AREA B-

3026,3031,3028,3033,3008,3010, 3030, 3035-ok

3011-address ledger connections at elevator,

3001- INSTALL MISSING FIRE DAMPERS

Corrective Action Required:

FOURTH FLOOR THE FOLLOWING AREAS ARE APPROVED

::AREA A:

4004-4006,4021-4025,4027,4002,4001,4013

AREA "B"

4008,4010,4011,4026,4028,4033,4030,4035-OK

4031-address main lugs at panel, joist hangers at deck tension tie joist

4001-INSTALL MISSING FIRE DAMPERS

4005-Provide access panels for j boxes in ceiling

4006-Seal penetrations

Corrective Action Required:

5 FIFTH FLOOR AREA "A"

THE FOLLOWING AREAS ARE APPROVED:

5004-5006,5021-5025,5027,5029

5013-Complete fresh air duct through ceiling, provide dampers

5001-INSTALL MISSING FIRE DAMPERS

AREA "B"

5033,5028,5026, 5031,5035,5030,5010,5007

5004-Provide dampers at ceilng

5005-Access panels and cover plates above ceiling

5006-Seal gaps at dampers

Corrective Action Required:

6 ELEVATOR 2 -WALL FRAMING OK FLOORS 2-4

**SEAL GAPS AT CEILING LINE

Comments: