CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20213548 Address: 2100 NW LOWENSTEIN DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Robb Popp	Partial	Friday, November 18, 2022
Corrective Action Required: 1 THIRD FLOOR	AREA A -RC AT UNITS AND CORRIDORS -1ST AND SECOND LAYER UNITS AND CORRIDOR AREA B: -RC AT UNITS AND CORRIDORS -1ST AND SECOND LAYER UNITS AND CORRIDOR		
Corrective Action Required: 2 SECOND FLOOR	AREA C -RC AT UNITS AND CORRIDORS 314-REPAIR ROCK AT CEILING IN KITCHEN AREA D -RC AT UNITS AND CORRIDORS AREA A -RC AT UNITS AND CORRIDORS -1ST AND SECOND LAYER CORRIDOR AND UNITS AREA B -RC AT UNITS AND CORRIDORS-FIRE BLOCK CEILING LINE AT SEPARA		NE AT SEPARATION

		WALLS -1ST AND SECOND LAYER UNITS AND CORRIDOR
		AREA C: -RC AT UNITS AND CORRIDORS 213-REPAIR ROCK AT CEILING BATH AND MECHANICAL 215-REPAIR ROCK AT CEILING KITCHEN AND MECHANICAL
		AREA D -RC AT UNITS AND CORRIDORS
Correctiv	e Action Required:	
3 FIRST FLOOR	AREA A	
	-RC AT UNITS AND CORRIDOR EXCEPT AS NOTED:	
		129 INCOMPLETE -1ST LAYER AND SECOND LAYER AT UNITS AND CORRIDOR EXCEPT AS NOTED: 129 INCOMPLETE
		AREA B
		-CLUBHOUSE TRUSSES OK FOR PRE ROCK
	-SCREW PATTERN AT AMENITIES CEILINGS	
		-RC FOR UNITS AND CORRIDORS-NO COMMON AREAS -FIRST LAYER AND SECOND LAYER AT UNITS AND CORRIDOR-NO COMMON AREAS
		AREA C:
		-RC AT UNITS AND CORRIDORS
		112-SCREW ROCK AT KITCHEN/CORRIDOR CORNER
		114-REPAIR ROCK AT CEILING

REPAIR ROCK AT SPRINKLER HEAD

Comments: