Bi-monthly Special Inspection Report



Permit #: PRCOM20222242

Project Address: 540 NE Town Centre Drive Lee's Summit, MO

Bi-monthly Report #: 10

Date: 12.16.2022

APEX ENGINEERS, INC.	Project Name: Agency Name:	Apex Engineers, I	ndoor Batting Cages nc	
	This report co	overs work completed	d between <u>12.01.2022</u>	_ and <u>12.15.2022</u>
	-	ed individual workin ne 2018 International		pected and/or tested the following items in
Attachment	ts (Concrete Break	Results, RFI's, etc.)	Shotcrete	
Placement	of Reinforced Conc	rete	None - No Inspection	ns made
Placement	of Shotcrete		Erection of Precast C	Concrete
Testing of F	Reinforced Concrete	e	Steel Frame Inspection	on
Placement	of Reinforcing Stee	I	High Strength Bolting	
Placement	of Prestressing Ste	el	Structural Welding	
Bolts Install	led in Concrete		Sprayed Fire Resista	nt Materials
Post-Install	ed Anchors		Structural Masonry	
Verification	of Soils		Wood Construction	
Excavation	and Filling		Seismic Resistance	
Deep Found	dations		Firestop	
Earth-Retai	ining Structures		Drill & Epoxy	
Detention B	Basin		INSPECTION OF FABRI	CATORS
EIFS			Metal Building	Structural Steel
Smoke Cor	ntrol		Wood Construction	Precast Concrete
X Other: Prod	of Roll			

Except where noted in the attached report, the work was found to be in substantial compliance with the city reviewed plans, specifications, and applicable provisions of the Building Code. All daily reports and EOR/AOR resolutions are attached.

m OHers

Denver, CO 720-588-3222

Kansas City, MO 816-421-3222

PE-200300000 2022.12.19 WARRENGE TO NAL ENGRAPHICA 795-337-32 Lawrence, KS 785-337-3222

........

Non-Conforming Items Requiring Resolution



 Permit #:
 PRCOM20222242
 Date:
 12.15.2022

 Project Address:
 540 NE Town Centre Drive Lee's Summit, MO
 12.15.2022

Project Name: New Building for Indoor Batting Cages

Agency Name: Apex Engineers, Inc Insp/Engr: Clayton J. Hess

Final Approval Status:

Item	Date	Report	Discrepancy Description	Resolution Date
1	9/30/22	6	Various anchor bolts (CIP) were installed in the the incorrect location. Deferred to EOR for resolution.	Anchors post-installed and inspected per EOR and RFI.
2	12.13.2022	10	Member G23 was missing on Grid F from 6 to 7	
3	12.13.2022	10	Angle brace missing at Grids C.5/3 and A.2/6	

See attached details for further clarification

Daily Special Inspection Report Form

	Permit #: Project Address: Project Name: Agency Name:	PRCOM20222242		Date:	12-13-2022			
ADEV			tre Drive Lee's Summit, MO		9:30am			
APEA		Apex Engineers, In	door Batting Cages		11:30am Chris Walker			
NGINEERS, INC.	Agency Name.	Apex Engineers, in	ic.	iiisp/Liigi.	CIIIS Waikei			
REINFORCED (Placement of Placement of Testing of Reinforcing)	of Reinforced Cond of Shotcrete einforced Concret Steel Placement ed in Concrete g Concrete	crete	STRUCTURAL STEEL High Strength Bolting Welding of Structural Steel Metal Deck Welding Shear Stud Welding Welding of Reinforcing Steel Steel Frame Inspection SPRAYED FIRE RESISTANT	el	R MASTIC AND			
Verification of	of Soils		INTUMESCENT FIRE RESIST					
STRUCTURAL I	Piers asin hing Structure MASONRY f Rebar Placemer Grout Testing	nt/Grouting Smoke Control EIFS	Placement Inspection Density Tests Thickness Tests PRECAST CONCRETE Inspection of Erected Pane Welding of Panel Connecti INSPECTION OF FABRICATO Metal Building Wood Construction Seismic Resistance Drill & Epoxy	els ons	emperature Steel ncrete			
List locations of inspections/tests made: Steel framing inspection of the member sizes, location and layout for the roof, walls and column supports of the building. The bolted connections were not checked throughout the building due to access and construction debris on the floor. The contractor will have it accessible during the re-inspection for the missing framing members.								
1. Were there any discrepancies with the reviewed plans? 2. Were there any changes to the reviewed plans? 3. Were any previously listed items corrected or resolved? 4. Are the signed/sealed resolutions by the EOR/AOR attached? If yes, on items 1, 2, or 3, describe below:								
1) Member G23 was missing on Grid F from 6 to 7 2) Angle brace missing at Grids C.5/3 and A.2/6								
Inspector: Chris	Walker	Signat	ure:					