WATER UTILITIES LEE'S SUMMIT

1200 SE Hamblen Road | Lee's Summit, MO 64081 P: 816.969.1900 | F: 816.969.1935 backflow@cityofls.net | LSwater.net

Backflow Prevention Assembly Test Data & Maintenance Report

Backflow Prevention Assembly	lest Data & Maintenance 113		
John trot Village Meadows ervice Address	2		
520 NW HOPE Ln			
ocation of Backflow Assembly on Property			
nearly 10 moter	Air Gap (2 x Supply Diameter)		
Date of Test Time AM Supply Pressure	ir Gap (2 x Supply Diameter) Ipply: n/a IN. Gap: n/a IN.		
1-11-12 2:00:PM	Model Size Serial Number		
Manuacturer	2 11 4 5 6 2	QU	
ype of Assembly DC DCDA (Detector) RP RP RP RP RP RP RPDA (Detector)	850 2	01	
DCDA (Detector) PVB* (See Bottom of Form)	New Installation	on	
Protection From	Supply Source Both Public Potable Water	☐ NO	
Freezing: Yes No Flooding: Yes No	Non-Potable Water (e.g., LAKE)	ed Failed	
Passed Failed	l Final Test After Repair		
nital Test Reduced Pressure Principle Assembly:	Reduced Pressure Principle Assembly:		
RELIEF VALVE opened atPSID (2 PSID or more)	RELIEF VALVE opened atPSID (2 PSID or more)		
and CUECK held backpressure	2nd CHECK held backpressure		
NO 2 SHUTOFF VALVE leak tight	NO. 2 SHUTOFF VALVE leak tight 1st CHECK held in direction of flowPSID (5 PSID or more)		
tet CHECK held in direction of flow PSID (5 PSID or more)	DIFFERENCE (1st check - relief) PSID (3 PSID or more)		
DIFFERENCE (1st check - relief) PSID (3 PSID or more)	Note: Failure of any of the above items, requires repair.	_	
Note: Failure of any of the above items, requires repair.	Dans	sed Failed	
Passed Faile	d Final Test After Repair		
Initial Test Double Check Valve Assembly:	Double Check Valve Assembly: 1st CHECK held in direction of flowPSID (1 PSID or more)		
1 - CUECK held in direction of flow 2. (2 PSID (1 PSID or more)	2nd CHECK held backpressure		
a LICUTOV hold hackpressure	2nd CHECK field backpressare 2nd CHECK held in direction of flowPSID (1 PSID or more)		
PSID (1 PSID or more)	NO. 2 SHUTOFF VALVE leak tight		
NO 2 SHUTOFF VALVE leak tight	Note: Failure of any of the above items, requires repair.		
Note: Failure of any of the above items, requires repair.	Note: Failure of any		
Application: Comments			
Commercial			
✓ Irrigation			
Fire Line			
Fire Line By-Pass			
**Meter#			
**Meter Read	*		
Point of Use		40	
The Above Report is Certified to be True, Accurate and Complete	Repaired by (Print) (Signature) Date of Repa	air	
Tested By (Print) (Signature)			
Sulio Garag Julios	Final Test By (Print) (Signature) Date of Final	l Test	
Riue Cedar Landscape	Owner or Owner's Representative Date		
Missouri Certification Number	12-2	12-21-202	
33-12638 05-31-202	4 Paralaced by a DC or RP to meet current State and City regulate	tions.	
*If an existing PVB is beyond repair and needs replacement, it sho	ould be replaced by a DC or RP to meet current State and City regular replacements are not permitted.		
**METER # and METER READ for the fire line	replacements are not permitted. e by-pass meter on detector assemblies are required. o report results of tests and inspections to the customer and water s	upplier.	
Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to	e by-pass meter on detector assemblies are required. o report results of tests and inspections to the customer and water s WHITE - Water Supplier CANARY - Owner	Version: 20	
Distripution:	Milit - Marci pobbas.		