

Saint Mary's Lumber Jason Gaggero 707 E Hwy 24 Saint Mary's Ks 66536 6/28/23

RE:

Drippe Homes 3223 Enoch

Lee's Summit, MO

Permit #PRRES20226253

Dear Jason,

Today, as per your request, I reviewed the damaged joist in the home listed above. The joist is above the foot of the stairs, the bottom flange is damaged, and the framer has attached some ¾" OSB to the side of the joists. The compromised joist and the joist next to it are doubled for extra support of the fireplace walls and the fireplace itself. We doubled these joists because we didn't know the extent of the load the fireplace and walls might add. The load from these items is minor therefore the joists didn't need to be doubled. Please see the attached Forte calc sheet for the loading particulars.

Feel free to call with any questions you might have.

Thank you for choosing Trus Joist and Forest Products Supply.

Regards

Paul Cast FP/KC