

Inspection Summary

Building B:
-Shear walls behind tubs

		-1st layer behind tubs
Corrective Action Required:		
6	ELEVATOR 1	*Elevator 1 in building A -Sheet rock nailing pattern at rim joist 1st and 2nd layer exterior side for trusses -1st layer at walls -1st layer at ceiling
Corrective Action Required:		
9	STAIR TOWER 1	*Stair A building A -Shear wall nailing pattern at stair side of Stair A1 -1st and second layer walls at stair side, Stair A1 -2nd layer on east stair side screw pattern ok -1st layer at all walls 1st and 2nd floor
Informational:		
10	STAIR TOWER 2	*Stair B in building B -1st and 2nd layer stringer side only
Informational:		
11	STAIR TOWER 3	Stair 2B in building B -1st and 2nd layer stringer side only
Informational:		
12	STAIR TOWER 4	*Stair D in building D -1st layer stringer side only
Informational:		
13	STAIR TOWER 5	Stair E building E -Shear wall nailing pattern approved

Comments: