



# Structural Steel Inspection

Alpha Omega Geotech, Inc  
1701 State Avenue  
Kansas City, KS 66102  
Phone: 913-371-0000

Client:  
Saint Luke's Health System  
901 E 104th St  
Kansas City, MO 64131

Project:  
220475  
St Luke's East ASC Expansion  
100 NE St Lukes Blvd  
Lee's Summit, MO 64086

Date: 01/31/2024

Inspector: Steve Usnick, P.E.

## OBSERVATIONS

**Items Observed:** Welds on south canopy connecting to building.

**Method Of Inspection:**  
Visual Welds

**Type Of Connection:** Fillet

**Approximate Amount Of Items Inspected:**  
95%

**Discrepancy:** No

**Remarks:** None

Reviewed by: Steve Usnick, P.E.,  
02/01/2024



# Structural Steel Inspection

Alpha Omega Geotech, Inc  
1701 State Avenue  
Kansas City, KS 66102  
Phone: 913-371-0000

Client:  
Saint Luke's Health System  
901 E 104th St  
Kansas City, MO 64131

Project:  
220475  
St Luke's East ASC Expansion  
100 NE St Lukes Blvd  
Lee's Summit, MO 64086

Date: 12/18/2023

Inspector: Steve Usnick, P.E.

## OBSERVATIONS

**Items Observed:** Parapet wall support stub columns to embed plate welds.

**Method Of Inspection:**  
Visual Welds

**Type Of Connection:** Fillet

**Approximate Amount Of Items Inspected:**  
90%

**Discrepancy:** Yes

**Remarks:**

Waiting on an RFI from the engineer of record for fix or approval of welds on the building side of the supports that did not set completely on the embed plates. One side of the required 3 sides were not made in several locations.



# Structural Steel Inspection

Alpha Omega Geotech, Inc  
1701 State Avenue  
Kansas City, KS 66102  
Phone: 913-371-0000

Client:  
Saint Luke's Health System  
901 E 104th St  
Kansas City, MO 64131

Project:  
220475  
St Luke's East ASC Expansion  
100 NE St Lukes Blvd  
Lee's Summit, MO 64086

## DISCREPANCIES

**Discrepancy Number:** 1

**Discrepancy Status:** Open

**Discrepancy Description:**

Waiting on an RFI from the engineer of record for fix or approval of welds on the building side of the supports that did not set completely on the embed plates. One side of the required 3 sides were not made.

Reviewed by: Steve Usnick, P.E.,  
12/26/2023



# Structural Steel Inspection

Alpha Omega Geotech, Inc  
1701 State Avenue  
Kansas City, KS 66102  
Phone: 913-371-0000

Client:  
Saint Luke's Health System  
901 E 104th St  
Kansas City, MO 64131

Project:  
220475  
St Luke's East ASC Expansion  
100 NE St Lukes Blvd  
Lee's Summit, MO 64086

Date: 12/18/2023

Inspector: Steve Usnick, P.E.

## OBSERVATIONS

**Items Observed:** Parapet wall support stub columns to embed plate welds.

**Method Of Inspection:**  
Visual Welds

**Type Of Connection:** Fillet

**Approximate Amount Of Items Inspected:**  
90%

**Discrepancy:** Yes

**Remarks:**

Waiting on an RFI from the engineer of record for fix or approval of welds on the building side of the supports that did not set completely on the embed plates. One side of the required 3 sides were not made in several locations.



# Structural Steel Inspection

Alpha Omega Geotech, Inc  
1701 State Avenue  
Kansas City, KS 66102  
Phone: 913-371-0000

Client:  
Saint Luke's Health System  
901 E 104th St  
Kansas City, MO 64131

Project:  
220475  
St Luke's East ASC Expansion  
100 NE St Lukes Blvd  
Lee's Summit, MO 64086

## DISCREPANCIES

**Discrepancy Number:** 1

**Discrepancy Status:** Close

**Discrepancy Description:**

Waiting on an RFI from the engineer of record for fix or approval of welds on the building side of the supports that did not set completely on the embed plates. One side of the required 3 sides were not made.