

REINFORCING STEEL OBSERVATIONS REPORT

Report Number: 02231387.0008
Service Date: 03/11/24
Report Date: 03/14/24



15620 W 113th St
Lenexa, KS 66219-5102
913-492-7777

Client

The Summit Church
Attn: Robin Dawson
3381 NW Chipman Road
Lee's Summit, MO 64081

Project

The Summit Church Maintenance Facility
3381 NW Chipman Road
Lee's Summit, MO 64081

Project Number: 02231387

General Information

Steve Skinner requested Terracon to be on site for reinforcing steel observation of the following elements: continuous footing. These elements are being constructed by Steve Skinner. The results of observation(s) for today were reported to Steve Skinner.

The construction documents referenced for this observation include: Structural plans dated 1/17/2022.

Reinforcing Steel

Terracon observed reinforcing steel detailed below for the following items (as applicable): grade, configuration, size, lap length, quantity, spacing, tying, clearances, steel condition and embedded items.

Element	Location	Referenced Documents	Status	Comments
Continuous footing	(1) Maintenance building footing	S1.10	Complies	

Compliance Statement

Based on our observations, reinforcing steel at the above-referenced locations appeared to be completed in general accordance with the project plans and specifications.

Services:

Terracon Rep.: Sydney Christopher

Reported To: Steve Skinner

Contractor: Steve Skinner

Report Distribution:

(1) The Summit Church,
rdawson@reachingthesummit.com

(1) Steve Skinner Construction,
sskinnerconst@gmail.com

Reviewed By:

Leonard J. Rewerts
Senior Project Manager/Geologist

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

Photo Log

Report Number: 02231387.0008

Service Date: 03/11/24

Report Date: 03/14/24



15620 W 113th St
Lenexa, KS 66219-5102
913-492-7777



(P1) Footing for maintenance building



(P2) Footing for maintenance building