CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20240118

Address: 515 NW MOORE ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Inspection Robb Popp Partial Friday, January 03,

2025

Corrective Action Required:

1 Misc -Complete fur downs around plumbing etc, seal penetrations at corridors

Corrective Action Required:

2 ELEVATOR 1

Corrective Action Required:

3 ELEVATOR 2

Corrective Action Required:

4 STAIR TOWER 1

Corrective Action Required:

5 STAIR TOWER 2

Corrective Action Required:

6 STAIR TOWER 3

Corrective Action Required:

7 FIRST FLOOR -RC at ceiling joists and 16" below ceiling at corridor walls from 135-108

-Screw pattern at corridor ceiling ok

Informational:

8 SECOND FLOOR -RC at ceiling joists and 16" below ceiling at corridor walls from 235-208

-Screw pattern at corridor ceiling ok

-Screw pattern at corridor ceiling ok

Informational:

9 THIRD FLOOR -RC at ceiling joists and 16" below ceiling at corridor walls from 335-308

-Screw pattern at corridor ceiling ok

-Pre rock behind showers at 335-332

Informational:

10 FOURTH FLOOR

-RC at ceiling joists and 16" below ceiling at corridor walls from 435-408

-Screw pattern at corridor ceiling ok -Pre rock behind showers at 435-416

-North mechanical shaft- 1st layer at ceiling

**RC at units ceilings- secure all rc channel, support ends throughout,

maintain 16" oc max spacing

Comments: