CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20240118 Address: 515 NW MOORE ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Thursday, January 16, 2025
Corrective	Action Required:			
1	Misc	-Complete fur downs arou	ind plumbing etc, seal pene	trations at corridors
Corrective Action Required:				
2	ELEVATOR 1			
Corrective	e Action Required:			
3	ELEVATOR 2			
Corrective Action Required:				
4	STAIR TOWER 1			
Corrective	Action Required:			
5	STAIR TOWER 2			
Corrective	Action Required:			
6	STAIR TOWER 3			
Corrective Action Required:				
7	FIRST FLOOR	-RC at ceiling joists and 16 -Screw pattern at corridor	" below ceiling at corridor v ceiling ok	valls from 135-108
Informatio	onal:			
8	SECOND FLOOR	-RC at ceiling joists and 16 -Screw pattern at corridor -Screw pattern at corridor	-	valls from 235-208
Informatio	onal:	,	J	
9	THIRD FLOOR	-RC at ceiling joists and 16 -Screw pattern at corridor	" below ceiling at corridor v ceiling ok	valls from 335-308

		-Pre rock behind showers at 335-332
Informat	ional:	
10	FOURTH FLOOR	 -RC at ceiling joists and 16" below ceiling at corridor walls from 435-408 -Screw pattern at corridor ceiling ok -Pre rock behind showers at 435-416 -North mechanical shaft- 1st, 2nd, 3rd layer at ceiling **RC at units and corridor to Fire wall only ok to cover except outside of 414-Repair damaged dwv and replace strap and bocca plate, - Collers od DWV in chases in all 4 floor units complete Except unit 416, 422 waiting on engineers

Comments: