

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20240118
Address: 515 NW MOORE ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Robb Popp	Partial	Thursday, January 23, 2025

Corrective Action Required:

1 Misc -Complete fur downs around plumbing etc, seal penetrations at corridors

Corrective Action Required:

2 ELEVATOR 1

Corrective Action Required:

3 ELEVATOR 2

Corrective Action Required:

4 STAIR TOWER 1

Corrective Action Required:

5 STAIR TOWER 2

Corrective Action Required:

6 STAIR TOWER 3

Corrective Action Required:

7 FIRST FLOOR -RC at ceiling joists and 16" below ceiling at corridor walls from 135-108
-Screw pattern at corridor ceiling ok

Informational:

8 SECOND FLOOR -RC at ceiling joists and 16" below ceiling at corridor walls from 235-208
-Screw pattern at corridor ceiling ok
-Screw pattern at corridor ceiling ok

Informational:

9 THIRD FLOOR -RC at ceiling joists and 16" below ceiling at corridor walls from 335-308
-Screw pattern at corridor ceiling ok

-Pre rock behind showers at 335-332
-RC at units and corridor except as noted:

*Complete Hat channel assembly at 322,334,311
316-Support ends at living room and bathroom
321-Support ends at office

Informational:

10 FOURTH FLOOR

-RC at ceiling joists and 16" below ceiling at corridor walls from 435-408
-Screw pattern at corridor ceiling ok
-Pre rock behind showers at 435-416
-North mechanical shaft- 1st, 2nd, 3rd layer and hat channel at ceiling
**RC at units and corridor to Fire wall only ok to cover

**Update plans for new UL assembly on corridor and dividing walls

Comments: