

- Bore new 1.25" duct

- Replace damaged 72ct with 144ct
from HH 1800 to HH 3953

- Swing new 144ct into each existing
HH along NW Ward Rd

