CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242945

Address: 3718 SW KNOXVILLE CT, LEES SUMMIT, MO 640823716 SW KNOXVILLE CT, LEES SUMMIT, MO

64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Occupancy Inspection - Codes Residential Kyle Beard Failed Monday, February 03, 2025 Corrective Action Required: Miscellaneous 3716 Correction • Seal penetrations in garage ceiling at overhead door track brackets Back patio steps are on the wrong side of door exiting the house Microwave plug is not installed Anti hammer arrestor under sink is not installed Anti hammer arrestor under sink is not installed Secondly lock at patio door is not installed Utility room washer anti hammer devices are not installed Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer Seal hatch under stairs in basement	Inspection:		Inspector:		Outcome:	Date:	
Miscellaneous Correction Seal penetrations in garage ceiling at overhead door track brackets Back patio steps are on the wrong side of door exiting the house Microwave plug is not installed Anti hammer arrestor under sink is not installed Secondly lock at patio door is not installed Utility room washer anti hammer devices are not installed Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer			Kyle Bear	rd	Failed		
Correction Seal penetrations in garage ceiling at overhead door track brackets Back patio steps are on the wrong side of door exiting the house Microwave plug is not installed Anti hammer arrestor under sink is not installed Secondly lock at patio door is not installed Utility room washer anti hammer devices are not installed Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer	Corrective	e Action Required:					
 Back patio steps are on the wrong side of door exiting the house Microwave plug is not installed Anti hammer arrestor under sink is not installed Secondly lock at patio door is not installed Utility room washer anti hammer devices are not installed Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 	1	Miscellaneous	3716				
 Microwave plug is not installed Anti hammer arrestor under sink is not installed Secondly lock at patio door is not installed Utility room washer anti hammer devices are not installed Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 		Correction	•	Seal penetrati	eal penetrations in garage ceiling at overhead door track brackets		
 Anti hammer arrestor under sink is not installed Secondly lock at patio door is not installed Utility room washer anti hammer devices are not installed Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 			•	Microwave plug is not installed Anti hammer arrestor under sink is not installed Secondly lock at patio door is not installed			
 Secondly lock at patio door is not installed Utility room washer anti hammer devices are not installed Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 			•				
 Utility room washer anti hammer devices are not installed Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 			•				
 Seal hatch under stairs in basement Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 			•				
 Sump pump extension is not long enough (3ft minimum) 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 			•				
 3718 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 			•	Seal hatch under stairs in basement			
 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 			•	Sump pump extension is not long enough (3ft minimum)			
 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 							
 Patio door missing secondary lock Electrical face plate for refrigerator is not installed Anti hammer 			3718				
Electrical face plate for refrigerator is not installed Anti hammer			•	Patio door missing secondary lock			
· · · · · · · · · · · · · · · · · · ·			•		•	: installed Anti hammer	
			•				
Electrical panel is not installed			•	Electrical pane	el is not installed		

Both units

sod and splash pads are not installed

- Land sewer tracer wire in boxes
- Side walks are not installed
- Driveway finals are not completed
- Plot has not had final grading

Comments: