## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20235207 Address: 2931 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Khanh Nguyen	Partial	Tuesday, April 08, 2025
Corrective Action Required:			
1 LOWER LEVEL	-Tub&shower walls -mud&taped		
Corrective Action Required:			
2 FIRST FLOOR	-Tub&shower walls -mud&taped		
Corrective Action Required:			
3 SECOND FLOOR	-Tub&shower walls -mud&taped		
Corrective Action Required:			
4 THIRD FLOOR	-Tub&shower walls -mud&taped		
Corrective Action Required:			
5 FOURTH FLOOR	-Tub&shower walls -mud&taped		
Corrective Action Required:		k *	
6 STAIR TOWER 2	**THIS IS SOUTH STAIR A'		
	Lower floor:		
	-stair side 2nd layer		
	stan side zha ayer		
	1st floor:		
	-stair side 2nd layer		
	,		
	2nd floor:		
	-stair side 2nd layer		
	3rd floor:		

Connective Action Deswined	-stair side 2nd layer		
Corrective Action Required: 7 STAIR TOWER 3 Corrective Action Required:	**THIS IS REAR STAIR B**		
8 ELEVATOR 1	Lower floor: -004 dwelling side 2nd layer		
	1st floor: -104 dwelling side 2nd layer		
	2nd floor: -207/209 dwelling side 2nd layer		
	3rd floor: -307/309 dwelling side 2nd layer		
Corrective Action Required: 9 STAIR TOWER 1	4th floor: -405/407 dwelling side 2nd layer		
	**THIS IS NORTH STAIR A**		
	Lower floor: -stair side 2nd layer		
	1st floor: -stair side 2nd layer		
	2nd floor: -stair side 2nd layer		
Corrective Action Required:	3rd floor: -stair side 2nd layer		
10 Misc	Corridor fire barrier: -1st, 2nd floor ceiling nailing		

Comments: