## STORMWATER CONSTRUCTION SITE INSPECTION REPORT

GENERAL INFORMATION													
Project Name: Waterway Carwash													
Location: 1000 NW Pryor Rd., Lee's Summit, MO 64081													
Date of I	nspection: 04/24	/2025		Start/End Time: 7:30 am – 3:30 pm									
Inspectors' Name: Genovevo Ruiz													
Inspector's Title: Superintendent/PM													
Inspector's Contact Information: gruiz@wrightbuildingsystems.com/ 636-551-0215													
Describe present phase of construction:													
Site preparation of the sub grade for compaction and begin infill.													
Type of Ir	rspection:												
-	Regular	ent	t During storm event				Post-storm event						
WEATHER INFORMATION													
Has there If yes, pro	e <b>been a storm eve</b> ovide:	ent since the las	inspection?	<u>Yes</u> No									
Storm Start Date & Time:			Storm Dura	Storm Duration (hrs.):			Approx. Amount of Precipitation (in.):						
4/19 Start @ 9:00pm – 4/20 Fin @ 6:00 PM			9 hrs.	9 hrs.			1.9						
4/23 Morning and Evening Showers			1 hr	1 hr			0.32						
Weather	at time of this ins	pection?											
Clear	X Cloudy	Rain	Sleet	Fog		Snowing		High Winds					
Other:				Temperature:				Mild					
Have any discharges occurred since the last inspection? Yes No If yes, describe:													
Are there any discharges at the time of inspection? Yes No If yes, describe:													
			CERTIFICAT	TION STATEM	1ENT								
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."													
Genovevo Ruiz PM/Superintendent 04/24/2025													
	Signature	Prin	ed Name & Tit	ie	Date								

## **OVERALL SITE ISSUES**

Below are some general site issues that should be assessed during inspections. Customize this list as needed for conditions at your site.

BMP/activity	Implemented?		Maintenance Required?		Corrective Action Needed and Notes
1. All inactive slopes and disturbed areas have been stabilized.	<u>Yes</u>	No	Yes	No	
2. Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	Yes	<u>No</u>	Yes	<u>No</u>	
3. Are all sanitary waste receptacles placed in secondary containment and free of leaks?	<u>Yes</u>	No	Yes	<u>No</u>	
4. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	<u>Yes</u>	No	Yes	<u>No</u>	
5. Are discharge points and receiving waters free of any sediments deposits?	<u>Yes</u>	No	Yes	<u>No</u>	
6. Are storm drain inlets properly protected?	<u>Yes</u>	No	Yes	<u>No</u>	Keep debris from building up.
7. Is the construction exit preventing sediment from being tracked into the street?	<u>Yes</u>	No	<u>Yes</u>	No	A sweeper has been provided to clean any sediments tracked.
8. Is trash/litter from work areas collected and placed in covered dumpsters?	<u>Yes</u>	No	<u>Yes</u>	No	
9. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	Yes	<u>No</u>	Yes	<u>No</u>	Not yet required.
10. Are Vehicles and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious materials?	<u>Yes</u>	No	<u>Yes</u>	No	
11. Are materials that are potential stormwater contaminants stored inside or under cover?	<u>Yes</u>	No	<u>Yes</u>	No	
12. Are non-stormwater discharges (e.g., wash water, dewatering) properly controlled?	<u>Yes</u>	No	<u>Yes</u>	No	
13. (Other)	Yes	<u>No</u>	Yes	<u>No</u>	