


STORMWATER CONSTRUCTION SITE INSPECTION REPORT

GENERAL INFORMATION											
Project Name: Waterway Carwash											
Location: 1000 NW Pryor Rd., Lee's Summit, MO 64081											
Date of Inspection: 05/08/2025						Start/End Time: 7:30 am – 3:30 pm					
Inspectors' Name: Genovevo Ruiz											
Inspector's Title: Superintendent/PM											
Inspector's Contact Information: gruiz@wrightbuildingsystems.com / 636-551-0215											
Describe present phase of construction: Site infill soil at 10" +/- lifts getting compaction and moisture testing.											
Type of Inspection:											
Regular	X		Pre-Storm Event			During Storm Event			Post-storm Event		
WEATHER INFORMATION											
Has there been a storm event since the last inspection? Yes <u>No</u>											
If yes, provide:											
Storm/Rain Start Date & Time:				Storm Duration (hrs.):				Approx. Amount of Precipitation (in.):			
5/2 - Evening Light Showers				1 hr				0.02			
5/2 – 3:00 PM – 10:00 PM				7 hr				0.31			
Weather at time of this inspection?											
Clear	X	Cloudy	X	Rain		Sleet		Fog		Snowing	
Other:							Temperature:		Mild		
Have any discharges occurred since the last inspection? Yes <u>No</u>											
If yes, describe:											
Are there any discharges at the time of inspection? Yes <u>No</u>											
If yes, describe:											
CERTIFICATION STATEMENT											
<p>"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."</p>											
				Genovevo Ruiz				05/08/2025			
Signature				Printed Name & Title				Date			

OVERALL SITE ISSUES

Below are some general site issues that should be assessed during inspections. Customize this list as needed for conditions at your site.

BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes
1. All inactive slopes and disturbed areas have been stabilized.	<u>Yes</u> No	Yes No	
2. Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	Yes <u>No</u>	Yes <u>No</u>	
3. Are all sanitary waste receptacles placed in secondary containment and free of leaks?	<u>Yes</u> No	Yes <u>No</u>	
4. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	<u>Yes</u> No	Yes <u>No</u>	
5. Are discharge points and receiving waters free of any sediments deposits?	<u>Yes</u> No	Yes <u>No</u>	
6. Are storm drain inlets properly protected?	<u>Yes</u> No	Yes <u>No</u>	Keep debris from building up.
7. Is the construction exit preventing sediment from being tracked into the street?	<u>Yes</u> No	<u>Yes</u> No	A sweeper has been provided to clean any sediments tracked.
8. Is trash/litter from work areas collected and placed in covered dumpsters?	<u>Yes</u> No	<u>Yes</u> <u>No</u>	
9. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	Yes <u>No</u>	Yes <u>No</u>	Not yet required.
10. Are Vehicles and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious materials?	<u>Yes</u> No	<u>Yes</u> No	
11. Are materials that are potential stormwater contaminants stored inside or under cover?	<u>Yes</u> No	<u>Yes</u> No	
12. Are non-stormwater discharges (e.g., wash water, dewatering) properly controlled?	<u>Yes</u> No	<u>Yes</u> No	
13. (Other)	Yes <u>No</u>	Yes <u>No</u>	