Storm Water Inspection

JOB NUMBER: GX394

LOCATED AT: 500 SW LONGVIEW RD.

LEE'S SUMMIT, MISSOURI

DATE: 02/28/2025

RESULT: See below

NOTIFICATIONS

CONTACTED: RUSTY SHORTEN

SHAWN SCHMALSTIEG

CONTACT METHOD: EMAIL

INSPECTION COMPLETED BY: Chuck Stites

chucks@kvco.net

Kaw Valley Storm Water Site Inspection Form

	itaw t	ancy storm			ispection rouni	
			Gener	al Ir	nformation	
Proj	ect Name		MCC	LO	NGVIEW	
Loca	ation	500 S\	W LONGVIEW	V R	D. LEE'S SUMMIT, I	MISSOURI
Date	e of Inspection	02/28/2	5			
Insp	ector's Name, phone, email	Chuck Stites		91	3) 687-5616	chucks@kvco.net
Insp	ector's certification #	687F976C				
	se (e.g., initial grading): #					
	erosion control sheet(s)	EROSION CO	ONTROL			
	renced (e.g., EC08-EC13) e of Inspection:		<u></u>	اممدا	y/Biweekly \square post-	storm event
Typ	e of hispection.		Weather			storm event
Haci	there been a storm event si	nce the last insp		IIIIO		l No
	es, provide:	nee the fast msp	ection:			
Stor	m Date(s): Amount of pr	ecipitation (in):	gauge referer	nced	: STORMWATCI	Н
	ather at time of this inspecti			_		a.
⊠C1	•	ı ⊔ Partly Clou	ıdy ⊔F	Fog	\Box Snowing \Box	Sleet
□Ot	ther: STORMWATCH					Temperature: 64
	Erosio	on Controls Requ	ired by the SW	PPP	and/or Erosion Contr	ol Sheets
	Erosion Controls	1	Maintenance			
	Erosion Controls		Required?		Corrective Action i	Needed, Notes, (Helpful Tips)
	Are all required perimeter	⊠Yes □No	□Yes ⊠No			
1	controls (such as silt fence, wattles, berms) present and	□N/A				
	installed properly?					
	Are all disturbed areas,	⊠YES □ No	□Yes ⊠No	0		
	inactive for 14 days or more, properly stabilized	□N/A				
2	(steep slopes 7 days)?					
	Are all storm drain inlets	⊠Yes □No	□Yes ⊠ No)		
3	properly protected?	□N/A				
	Are the exits constructed	⊠Yes □ NO	☐ Yes ⊠No)		
	correctly (proper width,	□N/A				
4	length, slope, material? Is there track-out onto the					
	street?	□Yes ⊠No				
	Are stockpiles more than	⊠Yes □No				
_	50' from a storm drain?	□N/A				
5	Are inactive stockpiles stabilized and/or BMPs		□Yes ⊠ No			
	Installed down gradient?		□ res ⊠ No			
	Does the sediment basin	□Yes □ No	□Yes ⊠ No)		
6	have adequate storage	⊠N/A				
	capacity (3,600 cubic ft. /acre required)?					
	Are all ditch checks present	□Yes □ No	□Yes ⊠ No)		
	and installed or built	⊠N/A				
7	correctly? Are rock ditch checks	□Yes □ No	□Yes ⊠ No	,		
	faced with small (1" or	□ Yes □ No ⊠N/A	LIC3 MINC			
	less) clean rock?					

	BMPs					
	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed, Notes, (Helpful Tips)		
1	Trash/litter from work areas placed in covered container(s)?	⊠Yes □ No □N/A	□Yes ⊠No			
2	Are concrete washouts available, used, marked with a sign, & properly constructed (with liner)?	⊠Yes □No □N/A	□Yes ⊠No			
3	Are spill containment materials (spill kit) readily available for bulk liquids?	⊠Yes □No □N/A				
4	Are potential storm water contaminants stored under cover and away from waterways?	⊠Yes □ No □N/A	□Yes ⊠ No			
5	Are all Porta Potty away from and down gradient of storm water inlets? Porta Potty anchored?	☐ Yes ☐ No ☐ N/A ☐ Yes ☐ No	☐ Yes ⊠ No			
6	In MO, is a public notification sign installed at entrance? In KS, are NOI and SWPPP kept on site?	⊠Yes □ No □N/A	□Yes ⊠ No			
7	Are equipment fueling, cleaning, & maintenance areas free of spills, leaks?	⊠Yes □No □N/A				
8	Fuel tanks located away from waterways (min. 50') and storm drains? Tanks are double-walled, have secondary containment below, or contained by a berm?	⊠Yes □No □N/A ⊠Yes □No		FUEL IS BROUGHT IN ON SERVICE TRUCK		
9	Non-storm water discharges not allowed by the permit are present?	□Yes ⊠ No				
10	Dewatering being done without a control device (such as a filter bag)?	□Yes ⊠ No	□Yes ⊠ No			
11	other	□Yes □ No □N/A	□Yes □ No			

CERTIFICATION STATEMENT

I certify that this document and all attachments were prepared under my direction. The information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

PRINT Name and Title CHUCK STITES SWPPP INSPECTOR