

Stormwater Pollution Prevention Plan Inspection Report

Project Name and Location: Blackwell

Weather: 66	
	□Cloudy ⊠Sunny □Rain □ Snowing/ Snow cover
Date of inspection: 5/20/25	
Inspectors Name: Jessica Ekster	
Type of Inspection: Regular Rain event Othe	er:
Rain in last 24 hrs (inches): .74"	
Owner/Permittee: Griffin Riley	
Current Site Condition: Active	

BMP Checklist	Yes	No
Inlet Barriers	X	
Sediment Barriers	Ø	
Construction Entrance	X	
Stream Crossings		\boxtimes
Seed/Sod/Hydroseed/Mulch/Blanket		\boxtimes
Sediment Basins & Discharge Locations		\boxtimes
Borrow Areas		\boxtimes
General Site Conditions		\boxtimes
Concrete Washout	\boxtimes	

Current Construction/Active Areas:		
Vertical		

Problem Areas/Special Observations (Note problem areas ONLY below):

BMP	Location	Observation, Effectiveness, & Corrective Actions Ordered
Silt fence	Along curb	Repair a few areas where the fence has been damaged or un-trenched
Stabilize	In-active	Stabilize all areas that have been inactive for 14+ days- Weeds are not considered vegetation.
Stabilize	Swale	Stabilize swale on North end as soon as possible if work is done- More silt build up near pond from swale
Stabilize	Detention Ponds	Stabilize detention ponds asap- weeds are not considered vegetation
Streets/Inlets	Throughout Site	Clean streets and a few inlets with silt build up
Silt fence	Perimeter	Orange silt fence is not trenched in on East side of pond behind Residences- See picture below and noted on map

Have items noted on the last inspection been corrected? \Box Yes \boxtimes No (if no explain) : Need to stabilize in-active areas and det. ponds.

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 7 days, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

Signature: (

Welch Silt Fence & Erosion Control, LLC



