

EVREN APARTMENTS

ASI #2 Narrative

05.12.2025

- C02
 - o Added removal of existing public storm sewer
- C26
 - Revised retaining wall 3 spot elevations.
- C32
 - Revised conflicting sewer service flowline elevations.
- C56
 - Adjusted the sanitary sewer service flowline for Building 8.

ARCHITECTURAL

- A0.03-A0.06
 - Updated code area and occupant load calculations.
- A0.40
 - Updated details 3 & 4.
- A0.42
 - Updated details 3 & 6. Added information to details 1-7.
- A0.43
 - o Updated detail 1 in response to BECI Peer Review comments.
- A1.13 & A1.18
 - Revised type A unit bedroom flooring from carpet to vinyl plank in response to Cityscape Development request.
- A1.16
 - Updated laundry closet wall size to accommodate washer box in response to RFI 32.
- A1.19
 - \circ $\;$ Resized two kitchen cabinets in response to RFI 36.
- A2.10
 - \circ $\;$ Updated two dimensions at each end of the building
- A2.11
 - \circ $\;$ Updated two dimensions at each end of the building
 - Ensured washer/dryer location is graphically shown on A6 units on building plans.
 - Updated unit tag for Unit A6 Type A.
 - Updated laundry closet wall size in B3A units to accommodate washer box in response to RFI 32.



- A2.12-A2.14 , A2.21-A2.24, A2.31-A2.34, & A2.41-A2.45
 - Ensured washer/dryer location is graphically shown at A6 units on building plans.
 - Updated laundry closet wall size in B3A units to accommodate washer box in response to RFI 32.
- A2.40
 - Clarified curb elevation near accessible garage.
- A2.41
 - Added references to plan detail 5/A5.11 l in response to BECI Peer Review comments.
 - Shifted location of elevator lobby wall in coordination with Bldg D truss shop drawings.
- A2.42
 - Ensured retaining walls at ends of bldg are graphically shown on building plan.
- A3.10, A3.11, A3.20-A3.22, A3.30, A3.31, A3.40, & A3.41
 - Added parapet types and legend in coordination with roof truss shop drawings.
 - Revised parapet heights above stair cores at Bldg D to match Bldg C.
 - Added notes in response to BECI Peer Review comments.
 - Updated windows with transoms in response to BECI Peer Review comments.
- A4.10-A4.15
 - Updated windows with transoms in response to BECI Peer Review comments.
 - Updated window graphics.
- A4.14
 - Updated windows with transoms in response to BECI Peer Review comments.
 - Updated window graphics.
 - Section 26 Revised parapet height above stair core of Bldg D to match Bldg C.
- A4.31
 - Updated slabs shown on stair sections 1 & 2 in coordination with structural.
- A4.32
 - Sections 1 & 2 Revised parapet heights above stair cores at Bldg D to match Bldg C.
- A4.40-A4.43, A4.50
 - Updated elevator overhead height and number of hoistway beams in response to elevator shop drawings.
- A5.00
 - Updated details 4 and 6-8 in coordination with structural and in response to BECI Peer Review comments.
- A5.10
 - o Updated details in response to BECI Peer Review comments.
- A5.11
- Updated details 1-4 and added detail 5 in response to BECI Peer Review comments.
- A5.20

0

- o Updated details 1-15 in response to BECI Peer Review comments.
- A5.30
 - Updated details 1-11 in response to BECI Peer Review comments.
 - Added detail 12 in response to BECI Peer Review comments.



- A5.40
 - Updated details, and added details 9 & 10 in response to BECI Peer Review comments.
 Removed detail 2.
- A5.50
 - Updated details 3-9 in response to BECI Peer Review comments.
 - Added detail 10.
- A5.51
 - Updated details 2-5, & 8 in response to BECI Peer Review comments.
 - Added details 9-10.
- A5.53
 - Updated details 1, 3-9, and 11 in response to BECI Peer Review comments.
- A6.00
 - Updated door material for Unit Entry door U1.
 - Updated door types A, B, and J.
 - Added door abbreviations to sheet.
- A6.10
 - Updated windows with transoms in response to BECI Peer Review comments.
- A8.00, A8.02
 - Updated detached garage slab slope to 1/8" per foot in coordination with rebar shop drawings.
- A8.01
 - Updated detached garage slab slope to 1/8" per foot in coordination with rebar shop drawings.
 - Updated detail 12 in response to BECI Peer Review comments.
- A8.02
 - Updated maintenance building slab slope to 1/8" per foot in coordination with rebar shop drawings.
 - Updated section 12.
- A8.03
 - Updated dimensions for accessible work station.
 - Added dimension to fireplace wall.
 - Added exterior material legend to sheet.
- A8.04
 - Updated details in coordination with rebar shop drawings and in response to BECI Peer Review comments

STRUCTURAL

- S0.01
 - Modified Sheet Index
 - Modified Snow Load at Note 7.Q
- \$1.03
 - Added W8x24 hoist beam at Elevator Roof Framing Plan to match elevator shops



- S1.11
 - Modified Hanger changed to 2x10 ledger at Section 2
 - Modified Section 2 note indicating location at corridor instead of unit
 - o Added W8x24 hoist beam at elevator roof detail
 - Added 2x4 stud wall at Section 3
 - Added 2x4 stud wall at Section 3A
- \$1.20
 - Modified Section 4 and 5 from 2x beams to treated glulam beams to allow for architectural waterproofing detail.
- \$1.30
 - Added Dimensions at Section 2B
- \$2.10
 - Added Typical pilaster call-out
- S2.10A
 - Added Spread footing at ADA garage
 - Added Top of footing elevation notes at SW corner
 - Added Typical pilaster call-out
- \$2.11
 - Deleted Header at corridor to elevator lobby
- S2.12
 - Modified Header tags at corridor
 - Deleted Header at corridor to elevator lobby
- S2.13
 - Added Section 7A/S3.30 cuts at corridor
 - Deleted Header at corridor to elevator lobby
- \$2.14
 - o Deleted Header at corridor to elevator lobby
- \$2.20
 - Added Typical pilaster call-out
- \$2.21
 - Deleted Header at corridor to elevator lobby
- \$2.22
 - Deleted Header at corridor to elevator lobby
- \$2.23
 - Deleted Header at corridor to elevator lobby
- \$2.24
 - \circ $\,$ Deleted Header at corridor to elevator lobby
- \$2.30
 - Added Typical pilaster call-out
- S2.31
 - Deleted Header at corridor to elevator lobby
 - Modified Header at corridor to elevator lobby



- \$2.32
 - Deleted Header at corridor to elevator lobby
- S2.33
 - Added Header tag at corridor
 - Deleted Header at corridor to elevator lobby
- \$2.34
 - Deleted Header tag at corridor to elevator lobby
- \$2.40
 - Added Typical pilaster call-out
- \$2.41
 - Modified Header at door corridor to elevator lobby
 - Deleted Header at corridor to elevator lobby
- \$2.42
 - Modified Header at corridor to elevator lobby
 - Deleted Header at corridor to elevator lobby
- \$2.43
 - Deleted Header at corridor to elevator lobby
- \$2.44
 - Deleted Header at corridor to elevator lobby
 - Added Header tag at corridor
- \$2.45
 - Deleted Header at corridor to elevator lobby
- \$3.03
 - Added Plan Detail 7 for pilaster reinforcing
- \$4.01
 - Modified Reinforcing added to Section 9

<u>MEP</u>

- P1.11
 - Relocate plumbing stacks per Arch and plumber coordination.
- P1.12
 - Relocate plumbing stacks per Arch and plumber coordination.
- P1.13
 - Relocate plumbing stacks per Arch and plumber coordination.
- P1.14
 - o Relocate plumbing stacks per Arch and plumber coordination.
- P1.15
 - Relocate plumbing stacks per Arch and plumber coordination.
- P1.21
 - Relocate plumbing stacks per Arch and plumber coordination.



• P1.22

• Relocate plumbing stacks per Arch and plumber coordination.

• P1.23

• Relocate plumbing stacks per Arch and plumber coordination.

• P1.24

Relocate plumbing stacks per Arch and plumber coordination.

• P1.25

0

• Relocate plumbing stacks per Arch and plumber coordination.

SPECIFICATIONS

• 012500 Substitution Procedures

 Added owner's building envelope consultant to review building envelope substitutions in response to BECI Peer Review Comments.

• 013300 Submittal Procedures

 Added owner's building envelope consultant to review building envelope submittals in response to BECI Peer Review Comments.

• 014000 Quality Requirements

• Added language to notify owner's building envelope consultant of opportunities to observe testing in response to BECI Peer Review Comments.

• 044313 Adhered Masonry Veneer

- Clarified metal flashing requirements.
- 071326 Self-Adhering Sheet Waterproofing
 - o Added installation language in response to BECI Peer Review comments.
 - Added testing in response to BECI Peer Review comments.
- 071416 Cold Fluid-Applied Waterproofing
 - Revised testing in response to BECI Peer Review comments.
- 072500 Weather Barriers
 - Added material compatibility requirements.
 - Added high performance installation requirements.

• 074646 Fiber-Cement Siding

- Added references to Divisions 1 and 7.
- Deleted spacers and insect screening language.
- Added language for fasteners to anchor into framing members.
- Added flashing installation information.
- 075423 Thermoplastic-Polyolefin (TPO) Roofing
 - Added testing in response to BECI Peer Review comments.
- 076200 Sheet Metal Flashing and Trim
 - Added information for installation of wall flashings at openings.
- 084113 Aluminum-Framed Entrances & Storefronts
 - Added references to Divisions 1 and 7.
 - Changed warranty period, added subsills, head receptor and break metal.
 - Added Sheet Metal specification reference and head receptors.



• Revised outswing thresholds to be thermally broken and offset, inswing revised to thermally broken.

• 085313 Vinyl Windows

• Added related specification references and examination and installation language.

• 103116 Manufactured Gas Fireplace

• Updated product section.