



This area is now a synthetic turf surface as shown on image 2.

This side to remain open. No handrail.

Existing Handrail on bldg facade

Ramp walk graded at maximum 8.33% with landings. Reinstalled to match previous condition.