

June 15, 2018

Corey Walker
M-II Longview, LLC
4220 Shawnee Mission Parkway, Ste. 200B
Fairway, KS 66205

Re: Site Visit – June 12th, 2017
Old Longview Lake Dam and Spillway
Lee's Summit, MO
Olsson Project No. 017-0305

As requested, Olsson Associates (**Olsson**) visited the project site on June 12th, 2018 to observe the existing condition of the Old Longview Lake Dam and Spillway. Our previous observation noted a syphon pump drawing down the lake. At the time of our current observation, we observed the lake to be around 3 to 5 feet lower in elevation as indicated by the staining on the structure shown in the Figure below.



In addition, the pipe was no longer drawing water from the lake due to clogging from vegetation. Moss is shown at the base of the hill where the pipe outlets. This is shown in the Figure below. We understand the water collection area is to be deepened and cleaned in order to continue syphoning.



No water was observed flowing over the blanket of the spillway or through the eroded area on the west side of the spillway. Visually, the dam, spillway and erosion channel do not appear to have changed since our initial visit. We have included a current photograph of the area below.



We appreciate the opportunity to be of service to you on this project. This letter has been prepared for the exclusive use of Platform Ventures for specific application to the project discussed and has been prepared in accordance with generally accepted geotechnical engineering practices. No warranties, express or implied, are intended or made. If you have any questions regarding this letter, please contact us.

Sincerely,

Olsson Associates

Kerri Kennedy
Staff Geologist

Ian Dillon, PE
Geotechnical Engineer