

DEVELOPMENT SERVICES

Residential Final Development Plan Applicant's Letter

Date: Tuesday, November 02, 2021

To:

Property Owner: CRCP INVESTMENTS LLC Email:

Applicant: ENGINEERING SOLUTIONS Email: MSCHLICHT@ES-KC.COM

Engineer: ENGINEERING SOLUTIONS Email: MSCHLICHT@ES-KC.COM

Architect: DAVIDSON ARCHITECTURE & Email: Justin@DavidsonAE.com

ENGINEERING

From: Victoria Nelson, Long Range Planner

Re:

Application Number: PL2021221

Application Type: Residential Final Development Plan **Application Name:** Chapel Ridge Townhomes, Phase 5

3701 NE AKIN DR, LEES SUMMIT, MO 64064 Location:

Electronic Plans for Resubmittal

All Planning application and development engineering plan resubmittals shall include an electronic copy of the documents as well as the required number of paper copies.

Electronic copies shall be provided in the following formats:

- Plats All plats shall be provided in mulit-page Portable Document Format (PDF).
- Engineered Civil Plans All engineered civil plans shall be provided in multipage Portable Document Format (PDF).
- Architectural and other plan drawings Architectural and other plan drawings, such as site electrical and landscaping, shall be provided in multi-page Portable Document Format (PDF).
- Studies Studies, such as stormwater and traffic, shall be provided in Portable Document Format (PDF).

Please contact Staff with any questions or concerns.

Excise Tax

On April 1, 1998, an excise tax on new development for road construction went into effect. This tax is levied based on the type of development and trips generated. If you require additional information about this development cost, as well as other permit costs and related fees, please contact the Development Services Department at (816) 969-1200.

Review Status:

Revisions Required: One or more departments have unresolved issues regarding this development application. See comments below to determine the required revisions and resubmit to the Development Services Department. Resubmit one (1) digital copy following the electronic plan submittal guides as stated above. Revised plans will be reviewed within five (5) business days of the date received.

Required Corrections:

Planning Review	Victoria Nelson (816) 969-1605	Long Range Planner Victoria.Nelson@cityofls.net	No Comments
Engineering Review	Loic Nguinguiri, E.I.	Staff Engineer Loic.Nguinguiri@cityofls.net	Corrections

- 1. Revise the overlapping information shown in profile view of sheet C.202 and the title block on C.402.
- 2. On the utility plan sheet (C.300), the water service line extending to the north shall not connect directly into the 8" gate valve. Please revise accordingly.
- 3. On the utility plan sheet (C.300), there appears to be multiple lines shown crossing Akin Dr. Please revise to only show the one existing line. The proposed service connection appears to be connecting to the FH apparatus. It should connect before and not directly to the apparatus. Revise the proposed connection details in this area to be more clear.
- 4. Sanitary pipe size(s) shown on the utility plan sheet (C.300) must match the ones shown on sheets C.401 and C.402.
- 5. Add an 18" crossing separation leader on to the profile view of sanitary line A at STA 3+03.60. Casing pipe should be used if the 18" (crossing) minimum separation requirement between utility pipes cannot be met. Make sure to also revise the sanitary profile view titles to mention "sanitary line B" and "sanitary line C".
- 6. Add the SAN-1, WAT-11 and WAT-12 construction standard details to the plan set.

Fire Review	Jim Eden (816) 969-1303	Assistant Chief Jim.Eden@cityofls.net	Approved with Conditions	
Traffic Review	Michael Park (816) 969-1820	City Traffic Engineer Michael.Park@cityofls.net	No Comments	
Building Codes Review	Joe Frogge (816) 969-1241	Plans Examiner Joe.Frogge@cityofls.net	Corrections	

1	Provid	le th	ne fo	llo	win	σ
ㅗ.	1 10010	וע נו	10 10	110	VV 11 1	೯.

-

- BFP type.

- BFP vault detail.

- Cleanouts in waste piping per spacing requirements of IPC 708.1.2 $\,$

10/4/21 - 0 out of 6 comments addressed.

10/27/21:

- BFP type not found

- BFP vault detail not found