

## ATC TOWER INSPECTION FORM



ANSI-TIA-222 Compliant

Page 1

## SECTION A - SITE INFORMATION

ATC Site Number	: 306042	ATC Site Name, State	: Woods Chapel, MO
Site Address	: 1204 N.e. Woods Chapel Road	Number of Compounds	:
City/State	: Summit, Jackson, MO 64064	Date of Inspection	: 03/31/2025
Contractor Name	: Tower Engineering Professionals	Tower Elevation Photo	: Woods Chapel MO (306042)_006.JPG
Inspection Completed By	: William Ducourant, Matthew Weber	SC Tagged Out?	: No

## SECTION B - TOWER INFORMATION

Structure Type	: Monopole	# of Tower Legs	: Monopole		
Tower Height	: 150.80'	Safety Climb Installed?	: Yes	Location:	Monopole face
Overall Structure Height	: 155.69'	Safety Climb Manuf.	: AllFasten	Climbing Facil.:	Step Bolts
Tower Manufacturer	: CNR	AM Detuning?	: No		

## SECTION C - SITE INFORMATION CATEGORIES

SECTION A - Site Information	SECTION G - Safety Comments
SECTION B - Tower Information	SECTION H - Grounding Comments
SECTION C - Tower Information Summary Comments	SECTION I - Guy Anchors & Wires Comments
SECTION D - Summary of Deficiencies	SECTION J - AM Detuning Comments
SECTION E - Tower Foundation Comments	SECTION K - Compliance
SECTION F - Tower Structure Comments	

## SECTION D- SUMMARY OF OBSERVATIONS

**Instructions:** List Comments in Sections E through J as applicable. Section D Summary will automatically populate.

1. [Corrected] - safety cable obstruction observed at 131', on Monopole face due to groundings, (Installed tuf-tug during	Photos:	Woods Chapel MO (306042)_206.JPG
2. [Corrected] - safety cable obstruction observed at 148', on Monopole face due to carrier mount, (Installed cable guide	Photos:	Woods Chapel MO
3. [Corrected] - safety cable obstruction observed at 121', 139', on Monopole face due to platform mount, (fixed by	Photos:	Woods Chapel MO
4. (5) Missing or damaged step bolt(s) were observed at 0'-150.8' on monopole face. Installed step bolts are standard	Photos:	Woods Chapel MO
5. Tower base grounding was observed to be inadequate, there are currently (2) installed properly. [(2) Damaged]	Photos:	Woods Chapel MO
6.	Photos:	
7.	Photos:	
8.	Photos:	
9.	Photos:	
10.	Photos:	
11.	Photos:	
12.	Photos:	
13.	Photos:	
14.	Photos:	
15.	Photos:	
16.	Photos:	
17.	Photos:	
18.	Photos:	
19.	Photos:	
20.	Photos:	

## SECTION E - TOWER FOUNDATION

**Instructions**

**Tower base** should be visually inspected for spalling and cracking of the concrete. The soil surrounding the tower base foundation should be inspected for evidence of settlement. Any such settlement or movement should be noted.

**Base drains (if present)** should be clear of any obstructions. Penetrate drain with object to ensure drains functioning.

**Base insulators (if present)** - The porcelain surface should be wiped clean with a soft cloth to remove any salt deposits or other foreign substance. A check should be made for any evidence of deterioration or cracks in the porcelain surface.

**All discrepancies must be marked with masking tape and magic marker.**

**All discrepancies must be noted and photographed and numbered.**

Is tower center pin in place?

Is tower center pin free of corrosion?

Are all base plate bolts, nuts, and washers present?

Is the tower foundation in good condition? (No cracking, spalling, or settling)

Is the concrete tower base free from standing water?

Are base drains clear and free flowing? (Drains required only under tubular legs.)

Is porcelain surface of base insulators in good condition? (No deterioration or cracking)

Is the soil around the foundation in good condition? (No settling or movement)

*If any comments exceed one row please expand the row height so that all of the text is visible. To expand rows automatically, click the Select All button, then click AutoFit Row Height in the Cells/Format box.*

**Comments:**

1.	Photos:
2.	Photos:
3.	Photos:
4.	Photos:
5.	Photos:
6.	Photos:
7.	Photos:
8.	Photos:
9.	Photos:
10.	Photos:

**Instructions**

Copyright © ATC IP, LLC - All Rights Reserved

**Corrosion** - If corrosion is observed, the source should be determined and noted.**Damaged or faulty members** - A visual inspection must be made of the entire tower structure to determine if any of the members have been deformed or damaged. Any bowed, bent or damaged member/bolt should be noted as to part number, size, location on tower, nature and magnitude of deformation or damage.**Do not remove any tower member for replacement unless authorized by ATC Engineering Dept - Signed/Sealed Construction Drawings are required if a****All discrepancies must be marked with masking tape and magic marker. All discrepancies must be noted and photographed before and after repair.**

Is the tower free of rust? (If "No", be specific in the comments below.)

Are all structural members straight and not damaged, bent, and/or missing?

Is the tower finish in good condition? (No obvious signs of cracking)

**Comments:**

1.	Photos:
2.	Photos:
3.	Photos:
4.	Photos:
5.	Photos:
6.	Photos:
7.	Photos:
8.	Photos:
9.	Photos:
10.	Photos:
11.	Photos:
12.	Photos:
13.	Photos:
14.	Photos:
15.	Photos:
16.	Photos:
17.	Photos:
18.	Photos:
19.	Photos:
20.	Photos:
21.	Photos:
22.	Photos:
23.	Photos:
24.	Photos:
25.	Photos:

**SECTION G - SAFETY****Instructions****Safety is paramount- Report anything that makes it unsafe to operate or maintain this tower to ATC immediately.****All discrepancies must be marked with masking tape and magic marker. All discrepancies must be noted and photographed before and after repair.**

Is there a safety climb system?

Are all components of the safety climb system free of rust?

Is the cable free from kinks, fraying, broken wires or strands or other damage?

Is the climbing path free from obstructions allowing a clear path for the cable?

Is the cable secured by properly spaced cable guides?

Is the total system properly installed including the top connection? If No, correct and note.

Is the FCC and ATC signage apparent and placed properly.

**Comments:**

1. [Corrected] - safety cable obstruction observed at 131', on Monopole face due to groundings, (Installed tuf-tug during	Photos: Woods Chapel MO
2. [Corrected] - safety cable obstruction observed at 148', on Monopole face due to carrier mount, (Installed cable guide	Photos: Woods Chapel MO
3. [Corrected] - safety cable obstruction observed at 121', 139', on Monopole face due to platform mount, (fixed by	Photos: Woods Chapel MO
4. (5) Missing or damaged step bolt(s) were observed at 0'-150.8' on monopole face. Installed step bolts are standard	Photos: Woods Chapel MO
5.	Photos:
6.	Photos:
7.	Photos:
8.	Photos:
9.	Photos:
10.	Photos:

**SECTION H - GROUNDING****Instructions****Connections** - The connections above grade should be visually checked for loose fittings, ensure wires are snug in mechanical connections or well bonded with exothermic connections at the base of the tower.**Ground Wires** - The ground wires at the base should be cad welded to each leg.

Take a photo of the grounding at the base and at each anchor.

**All discrepancies must be marked with masking tape and magic marker. All discrepancies must be noted and photographed before and after repair.**

Is the tower base properly grounded?

Are the guy cables and/or guy anchor heads properly grounded?

Are ground wires and connections in satisfactory condition?

Is the lightning rod mounted such that it is secured to the structure and not at risk of falling?

**Comments:**

1. Tower base grounding was observed to be inadequate, there are currently (2) installed properly. [(2) Damaged]	Photos: Woods Chapel MO
2.	Photos:
3.	Photos:
4.	Photos:
5.	Photos:
6.	Photos:
7.	Photos:
8.	Photos:
9.	Photos:
10.	Photos:

**Instructions**

Copyright © ATC IP, LLC - All Rights Reserved

All discrepancies must be marked with masking tape and magic marker and must be noted and photographed.

Are the guy cables & paths clear of brush, vegetation, fencing or any other obstruction?  
 Are the anchor heads and rods free from any bends and/or fractures?  
 Are the anchor heads and turnbuckle hardware free from soil build-up?  
 Are exposed guy anchor foundations free from cracking, weathering?  
 Do the turnbuckles have room for adjusting tensions? (Not fully extended or contracted?)  
 Are the anchor heads free of corrosion?  
 Is guy anchor rod laterally aligned?  
 Are guy wires free of broken strands or insulators?  
 Are the guy dampers secured and in good condition?  
 Are all shackles, clevises, thimbles, cotter pins, and Crosby clamps properly installed?  
 Are the dead-end grips in good condition?  
 Are the dead-end grip end-sleeves (ice-clips) installed?  
 Are guy wires and guy hardware free of corrosion?  
 Is each turnbuckle safety wire properly installed and secure? If not, make corrections.  
 Are guy wire connections in satisfactory condition?  
 Are guy attachment points to tower in good condition?

**Note - If anchor shafts show signs of heavy corrosion at any point, stop digging immediately and complete the remainder of the inspection.**

**Comments:**

1.	Photos:
2.	Photos:
3.	Photos:
4.	Photos:
5.	Photos:
6.	Photos:
7.	Photos:
8.	Photos:
9.	Photos:
10.	Photos:
11.	Photos:
12.	Photos:
13.	Photos:
14.	Photos:
15.	Photos:

**SECTION J - COMPLIANCE****By signing this report:**

- I understand that this information and form are the sole property of American Tower Corporation (ATC) and may not be copied or shared without written permission from ATC.

- I certify that any conditions or items omitted in this report were observed to be in acceptable condition per the criteria specified in the ATC Standard of Care and my own professional experience and judgement.

- I certify this report to be accurate and complete to the best of my knowledge and belief.

Name : Gautam Sopal

Date : 04/02/2025

Company : Tower Engineering Professionals