WATER UTILITIES
LEE'S SUMMIT

1200 SE Hamblen Road |Lee's Summit, MO 64081
P: 816.969.1900 | F: 816.969.1935
backflow@cityofls.net | LSwater.net

Backflow Prevention Assembly Test Data & Maintenance Report

Customer
The Social Salon and Spa

Service Address
808 SW Oldham Parkway

Location of Backflow Assembly on Property
SW corner of basement

Date of Test	*Time*	*Supply Pressure*	*Air Gap (2 x Supply Diameter)*
10/20/2020	11 : 00 ☑ AM ☐ PM	95 LBS	Supply: 3/4 " IN. Gap: Op IN. ☑ PASS ☐ FAIL

Type of Assembly	*Manufacturer*	*Model*	*Size*	*Serial Number*
☐ DC ☑ RP ☐ DCDA (Detector) ☐ RPDA (Detector) ☐ PVB* (See Bottom of Form)	Watts	LF-009M3QT	3/4 "	290117

Height off Floor	*Protection From*	*Supply Source*	*New Installation*
3 FT 0 IN	Freezing: ☑ Yes ☐ No Flooding: ☑ Yes ☐ No	☑ Public Potable Water ☐ Both ☐ Non-Potable Water (e.g., LAKE)	☑ YES ☐ NO

Inital Test	**Passed**	**Failed**
Reduced Pressure Principle Assembly:	☑	☐
RELIEF VALVE opened at 3.2 PSID (2 PSID or more)	☑	☐
2nd CHECK held backpressure	☑	☐
NO. 2 SHUTOFF VALVE leak tight	☑	☐
1st CHECK held in direction of flow 8.4 PSID (5 PSID or more)	☑	☐
DIFFERENCE (1st check - relief) 5.2 PSID (3 PSID or more)	☑	☐
Note: Failure of any of the above items, requires repair.		

Final Test After Repair	**Passed**	**Failed**
Reduced Pressure Principle Assembly:	☐	☐
RELIEF VALVE opened at _____PSID (2 PSID or more)	☐	☐
2nd CHECK held backpressure	☐	☐
NO. 2 SHUTOFF VALVE leak tight	☐	☐
1st CHECK held in direction of flow _____PSID (5 PSID or more)	☐	☐
DIFFERENCE (1st check - relief) _____PSID (3 PSID or more)	☐	☐
Note: Failure of any of the above items, requires repair.		

Initial Test	**Passed**	**Failed**
Double Check Valve Assembly:	☐	☐
1st CHECK held in direction of flow _____PSID (1 PSID or more)	☐	☐
2nd CHECK held backpressure	☐	☐
2nd CHECK held in direction of flow _____PSID (1 PSID or more)	☐	☐
NO. 2 SHUTOFF VALVE leak tight	☐	☐
Note: Failure of any of the above items, requires repair.		

Final Test After Repair	**Passed**	**Failed**
Double Check Valve Assembly:	☐	☐
1st CHECK held in direction of flow _____PSID (1 PSID or more)	☐	☐
2nd CHECK held backpressure	☐	☐
2nd CHECK held in direction of flow _____PSID (1 PSID or more)	☐	☐
NO. 2 SHUTOFF VALVE leak tight	☐	☐
Note: Failure of any of the above items, requires repair.		

Application:
- ☑ Commercial
- ☐ Irrigation
- ☐ Fire Line
- ☐ Fire Line By-Pass
  - **Meter # _____
  - **Meter Read _____
- ☐ Point of Use

Comments

The Above Report is Certified to be True, Accurate and Complete

Tested By (Print)	*(Signature)*	*Repaired by (Print)*	*(Signature)*	*Date of Repair*
Cameron Linton				
Company		*Final Test By (Print)*	*(Signature)*	*Date of Final Test*
MMC Contractors				
Missouri Certification Number	*Expiration Date*	*Owner or Owner's Representative*		*Date*
14-2204	6/30/2021	Unavailable		

*If an existing PVB is beyond repair and needs replacement, it should be replaced by a DC or RP to meet current State and City regulations. New PVB installations or replacements are not permitted.
**METER # and METER READ for the fire line by-pass meter on detector assemblies are required.
Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to report results of tests and inspections to the customer and water supplier.

Distribution: **WHITE** - Water Supplier **CANARY** - Owner